

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21004463/ATCE2**Date:** 07/09/2021**REFERENCE**

Insured/Claimant:	CHAN LEON CHI HONG	Policy No:	2070151560	
Date of Loss:	06/02/2021	Nature of Claim:	OD	Claim No: 6957542811SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJS1912T</b>		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZDC05420
Reg. Date:	28/10/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF32M1011498
Colour:	Grey	Odometer:	8591 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	17,979.00	5,044.76	12,934.24	71.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,592.00	3,922.00	4,670.00	54.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>26,571.00</b>	<b>8,966.76</b>	<b>17,604.24</b>	<b>66.25</b>
<b>- Excess (S\$)</b>	1,200.00	1,200.00	0.00	0.00
<b>(S\$)</b>	25,371.00	7,766.76	17,604.24	69.39
<b>+ GST 7.00/7.00% (S\$)</b>	1,775.97	543.67	1,232.30	69.39
<b>Nett Amount (S\$)</b>	<b>27,146.97</b>	<b>8,310.43</b>	<b>18,836.54</b>	<b>69.39</b>

**INSPECTION**

Date of Assignment:	08/04/2021		
Date Inspected:	07/04/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,161.00 FS	*922.00 FS
2	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	59.00 FS	*- FS
3	2		*FRONT BUMPER LOWER CLOSING ELEMENT - CENTER	Not Necessary	190.00 FS	*- FS
4	1		*FRONT BUMPER SPOILER	Not Necessary	383.00 FS	*- FS
5	1		*FRONT BUMPER AIR GRILLE - RH	Not Necessary	153.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE SECTION - RH	Cracked	39.00 FS	*30.48 FS
7	1		*FRONT FENDER	Dented	1,286.00 FS	*1,028.80 FS
8	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	63.00 FS	*- FS
9	1		*FRONT FENDER BRACE - RH	Bent	88.00 FS	*69.76 FS
10	1		*FRONT FENDER BRACKET - RH	Not Necessary	32.00 FS	*- FS
11	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	240.00 FS	*191.60 FS
12	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	101.00 FS	*- FS
13	1		*FRONT WHEEL HOUSING LINER COVER - RH	Not Necessary	16.00 FS	*- FS
14	1		*FRONT HEADLIGHT MOUNTING - RH	Not Necessary	118.00 FS	*- FS
15	1		*FRONT HEADLIGHT - RH	Not Necessary	5,589.00 FS	*- FS
16	1		*FRONT HEADLIGHT LIFT CYLINDER - RH	Not Necessary	210.00 FS	*- FS
17	2		*FRONT WHEEL ARCH TRIM - LH / RH	N/S Necessary / O/S Cut	536.00 FS	*428.80 FS
18	1		*FRONT DOOR - RH	Repair	2,805.00 FS	*- FS
19	1		*FRONT DOOR OUTER SEAL - RH	Not Necessary	166.00 FS	*- FS
20	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	157.00 FS	*- FS
21	1		*FRONT DOOR CATCH - RH	Not Necessary	120.00 FS	*- FS
22	1		*FRONT DOOR TYRE PRESSURE STICKER - RH	Not Necessary	30.00 FS	*- FS
23	1		*FRONT DOOR LOWER COVER - RH	Not Necessary	268.00 FS	*- FS
24	2		*FRONT TYRE RIM - LH / RH	Cut	2,524.00 FS	*2,019.20 FS
25	1		*FRONT TYRE - LH	Cut	345.00 FS	*345.00 FS
26	1		*SUNDRIES	Necessary	300.00 FS	*9.12 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 17,979.00 5,044.76**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTSS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,200.00	1,000.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, AND RHS FRONT DOOR	New	3,400.00	1,650.00
6	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	320.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,592.00</b>	<b>3,922.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >