

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDT 5110E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	DISTORTED	1,786.50	1,531.00
2	REAR BUMPER SIDE GUIDE @\$112.20 (CONSISTENT)	BENT	224.40	224.40
2	REAR BUMPER INNER GUIDE @\$95.60 (CONSISTENT)	NOT NECESSARY	191.20	-
1	REAR BUMPER CENTRE INNER BRACKET (CONSISTENT)	CRACKED	320.40	181.00
2	REAR BUMPER REFLECTOR @\$195.00 (CONSISTENT)	NOT NECESSARY	390.00	-
1	REAR BUMPER CENTRE LOWER GARNISH (CONSISTENT)	NOT FITTED	895.20	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	679.80	640.53
4	REAR BUMPER SENSOR (ORI) @\$263.10 (CONSISTENT)	SHORTED (4 PCS ONLY)	1,052.40	450.00
1	REAR BUMPER SENSOR HOLDER (CONSISTENT)	NOT NECESSARY	115.00	-
1	REAR BUMPER TOW (CONSISTENT)	TORN	110.00	38.00
1	SET REAR BUMPER BUMPER CLIPS (CONSISTENT)	NECESSARY	60.00	60.00
1	REAR BOOTLID PANEL (CONSISTENT)	BENT / BUCKLED	2,180.40	1,615.00
1	REAR BOOTLID INNER LOCK (CONSISTENT)	TWISTED	495.70	399.00
1	REAR BOOTLID LOCK SENSOR (CONSISTENT)	NOT NECESSARY	517.80	-
1	REAR BOOTLID LOGO (CONSISTENT)	NECESSARY	128.00	98.00
1	REAR BOOTLID EMBLEM (523I) (CONSISTENT)	NECESSARY	137.00	85.00
1	REAR BOOTLID WEATHERSTRIP (CONSISTENT)	TWISTED	468.60	288.00
2	REAR BOOTLID LAMP @\$783.00 (CONSISTENT)	NOT NECESSARY	1,566.00	-
2	REAR TAILLAMPS @\$1186.00 (CONSISTENT)	N/S CRACKED	2,372.00	685.00
1	REAR EXHAUST HEAT SHIELD (CONSISTENT)	NOT NECESSARY	320.10	-
1	REAR EXHAUST CHROME MUFFLER (CONSISTENT)	NOT NECESSARY	245.80	-
1	REAR END PANEL (CONSISTENT)	BADLY DENTED	989.00	989.00
1	REAR END PANEL TOP GARNISH (CONSISTENT)	SERVICEABLE	275.00	-
1	REAR END PANEL TOP GARNISH CLIPS (CONSISTENT)	NOT NECESSARY	60.00	-
1	REAR SPARE TYRE TOP BOARD (CONSISTENT)	WARPED	465.00	465.00
	LESS 5% DISCOUNT		-802.27	-387.45
			15,243.03	7,361.48

Report Ref No. CC4/ASM21004471/Uba3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	FRONT DRIVER SEAT HEAD -REST AIR BAG (REPAIR KIT) (SN) (CONSISTENT)	ACTIVATED	987.20	165.00
1	FRONT PASSENGER SEAT HEAD-REST AIR BAG (REPAIR KIT) (SN) (CONSISTENT)	ACTIVATED	826.70	165.00
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	50.00
1	REAR NUMBER PLATE W/BASE GARNISH (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
			1,973.90	380.00
	<u>LABOUR</u>			
	TO REMOVE ,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS .		1,200.00	800.00
	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS .		1,400.00	900.00
	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING .		50.00	30.00
	TO REMOVE & INSTALL REAR BOOTLID COMPONENTS TRIM & GARNISH .		150.00	60.00
	TO REMOVE & INSTALL REAR FENDERS TRIM GARNISH .		150.00	80.00
	TO REMOVE & REPLACE FRONT DRIVER SEAT HEAD - REST AIR BAG.}		150.00	80.00
	TO REMOVE & REPLACE FRONT PASSENGER SEAT HEAD-REST AIR BAG.}		150.00	-
	TO RE-PROGRAMME & RESET ECU DIAGNOSTIC.	NOT NECESSARY	480.00	-
	TO CONDUCT WATER LEAKAGE TEST .	NOT NECESSARY	150.00	-
	TO REMOVE ,INSTALL & RE-POSITION REVERSE SENSOR .		150.00	50.00
	TO RUST PROOF AFFECTED AREAS .		150.00	60.00
			4,180.00	2,060.00
	GRAND TOTAL		21,396.93	9,801.48

RECOMMENDED COST OF LUMP SUM REPAIRS	7,800.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM21004471/Uba3q2

CHUA KANG SENG

**Licensed Appraiser**