



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 2192K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	REAR TAILLAMP RH/LH @\$281.63 (CONSISTENT)	CRACKED	563.26	563.26
2	REAR TAILLAMP BRACKET RH/LH @\$268.06 (CONSISTENT)	BENT	536.12	536.12
1	REAR NUMBER PLATE LAMP (CONSISTENT)	CRACKED	78.68	78.68
	LESS 10% DISCOUNT		-117.81	-
	LESS 25% DISCOUNT		-	-294.52
			1,060.25	883.54
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR NUMBER PLATE WITH CASING (SN) (CONSISTENT)	CRACKED	45.00	40.00
1	SET REAR NUMBER PLATE BRACKET (SN) (CONSISTENT)	BENT	90.00	90.00
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	280.00	200.00
1	REAR STEP BRACKET (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	220.00	-
1	REAR FUSE BOX (SN) (CONSISTENT)	CRACKED	280.00	280.00
			915.00	610.00
<u>LABOUR</u>				
	TO KNOCK OUT DENT AND REPLACE ACCIDENT PARTS .INCLUSIVE OF THE REPAIR OF REAR STEP BRACKET.		350.00	300.00
	TO SPRAY PAINTING ON ACCIDENT PORTION .		350.00	250.00
	TO CHECK WIRING .		30.00	20.00
			730.00	570.00
GRAND TOTAL			2,705.25	2,063.54
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,650.00

Report Ref No. CC4/ASM21004472/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.