

ASS. REC. BY:

REF:

CC4/A1621004481/T1993

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	☒

Bal. or Market Value: \$60K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: szel

Vehicle: IN / OUT

Veh No: 6BH684267 Yr Regn: 2018, Aug.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV350 C.C. 2488Colour: 8/ner A/C: Insured / Std / NI / NA

Sp. Reading _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1MC2E26 20009009

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/80R16R: 195/80R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 8/4/21Survey held at Efficient Motor.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBH6842G

MAKE & MODEL : NV350 PANEL VAN 2.5 5MT 5DR

CHASSIS NO : JN1MC2E26Z0009009

DATE : 15 JAN 2021

CLAIM TYPE : TP CLAIM

D.O.A : 12 JAN 2021

TO : AIG Asia Pacific Insurance Pte. Ltd

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	REAR BUMPER		\$ 667.20	\$ del 667.20
2	6	REAR BUMPER SIDE CLIP LH/RH		\$ 12.10	\$ X 72.60
3	1	REAR BUMPER STEP PANEL		\$ 228.30	\$ bt 228.30
4	1	REAR END PANEL OUTER		\$ 324.00	\$ Rp 324.00
5	1	TAILGATE		\$ 2,160.00	\$ bt 2,160.00
6	1	TAILGATE LOCK LOWER		\$ 384.00	\$ X 384.00
7	1	TAILGATE LOCK UPPER		\$ 178.80	\$ X 178.80
8	1	TAILGATE LOCK COVER		\$ 84.00	\$ del 84.00
9	1	TAILGATE LOCK ACTUATOR		\$ 408.40	\$ X 408.40
10	1	TAILGATE STRIKER		\$ 51.50	\$ X 51.50
11	1	TAILGATE WEATHERSTRIP		\$ 228.00	\$ ant 228.00
12	1	TAILGATE CHROME GARNISH		\$ 535.70	\$ X 535.70
13	2	TAILGATE STAY LH/RH		\$ 215.90	\$ X 431.80
14	1	TAILGATE INNER TRIM BOARD		\$ 220.00	\$ X 220.00
15	1	TAILGATE LOGO		\$ 115.20	\$ del 115.20
16	1	TAILGATE EMBLEM "NV350 URBAN"		\$ 156.00	\$ del 156.00
17	1	TAILGATE INNER CENTER METAL COVER		\$ 108.00	\$ bt 108.00
18	2	TAIL LAMP LH/RH		\$ LHx 288.40	\$ RHx 576.80
				\$ 6,365.50	\$ 6,930.30

TOTAL PRICE	\$ 6,930.30
LESS 10%	\$ 693.03
SUB TOTAL PRICE	\$ 6,237.27

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	REAR BUMPER CLIPS		\$ 50.00	\$ 30 net 50.00
2	1	70 KM/H STICKER		\$ 20.00	\$ net 20.00
3	1	REVERSE SENSOR		\$ 200.00	\$ net 200.00
4	1	REAR NO. PLATE		\$ 45.00	\$ X 45.00
5	1	REAR WINDSCREEN SEALANT		\$ 150.00	\$ 60 net 150.00
6	1	REAR WOODEN FLOOR BOARD		\$ 250.00	\$ X 250.00
7	1	REAR PANEL CHECKER PLATE		\$ 80.00	\$ X 80.00

TOTAL S/NETT	\$ 795.00	\$ 795.00
--------------	-----------	-----------

Labour Charges

1	To cut/weld panels, panel beat & align tailgate, remove & replace damaged parts.	\$ 1,200.00	600
2	To apply anti rust coat and Tuff Kote repaired areas.	\$ 100.00	30
3	To check and rectify lighting & wiring.	\$ 50.00	30
4	To remove & replace reverse sensor.	\$ 100.00	30
5	To Spray painting for Rear Portions & affected areas.	\$ 1,000.00	700
6	To remove & transfer tailgate components.	\$ 150.00	60
7	To remove and replace rear windscreen glass.	\$ 150.00	120

TOTAL LABOUR	\$ 2,750.00
Total Cost of Repairs	\$ 9,782.27

(Total parts + Total S/Nett + Total Labour Cost)

Tanpin 27495441 'WP' 8/4/21 @ 530pm
 c/s Repairing after repair.
 5 days
 Tanpin @ Tanpin.com.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	635R

Vehicle Details

Vehicle No.:	GBH6842G
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jan 2021
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	YD25425426A
Chassis No.:	JN1MC2E26Z0009009
Maximum Power Output:	-
Open Market Value:	\$25,062.00
Original Registration Date:	23 Aug 2018
First Registration Date:	23 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$1,254.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	22 Aug 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$30,389.00
COE Rebate Amount:	\$23,102.00
Total Rebate Amount:	\$23,102.00

The information contained herein is correct as at 15 Jan 2021

OK