

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21004492/TEA3Q2**Date:** 13/06/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : GBJ2634G **Insured Vehicle No :** SLM9784B
 Date of Loss: 02/04/2021 Nature of Claim: TP Claim No: MFL2021D0001412

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ2634G**
 Make & Model: NISSAN NV350, 2.5 (A) Engine No: YD25041867B
 Reg. Date: 28/02/2019 (Man. Year: 2018) Chassis No: JN1MC2E26Z0030822
 Colour: White/Blue Odometer: 76712 km
 Engine Capacity: 2488 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Condor 6 mm Rear Left Side: Condor 6 mm
 Front Right Side: Condor 6 mm Rear Right Side: Condor 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,901.50	214.50	3,687.00	94.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,610.00	1,590.00	49.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,101.50	1,824.50	5,277.00	74.31
Approved Total (Overridden) (S\$)		1,450.00		
(S\$)	7,101.50	1,450.00	5,651.50	79.58
+ GST 7.00/7.00% (S\$)	497.11	101.50	395.61	79.58
Nett Amount (S\$)	7,598.61	1,551.50	6,047.11	79.58
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
Nett Liability (S\$)		1,871.50		

INSPECTION

Date of Assignment: 08/04/2021
 Date Inspected: 04/08/2021 Inspected At: Efficient Motor & Engineering Works Pte Ltd (HQ)
 56 Loyang Way #06-07, Loyang Enterprise Building
 Singapore 508775
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Jan 2022)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ2634G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP RH (WCP)	Not Necessary	120.00 F	*- F
2	1		*REAR BUMPER (WCP)	Repair	280.00 F	*- F
3	3		*REAR BUMPER SIDE CLIP RH (WCP)	Not Necessary	15.00 F	*- F
4	1		*REAR FENDER RH (WCP)	Repair	1,150.00 F	*- F
5	1		*REAR FENDER MUDGUARD RH (WCP)	Cut	75.00 F	*75.00 F
6	1		*RH SLIDE DOOR (WCP)	Not Necessary	750.00 F	*- F
7	1		*RH SLIDE DOOR ROLLER LOWER (WCP)	Not Necessary	65.00 F	*- F
8	1		*FUEL LID COVER (WCP)	Not Necessary	90.00 F	*- F
9	1		*RH REAR WHEEL HUB CAP (WCP)	Cut	120.00 F	*120.00 F
10	1		*FRT DOOR RH (WCP)	Not Necessary	700.00 F	*- F
11	1		*SET REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
12	1		*FRONT DOOR CO.REG STICKER	Not Necessary	30.00 FS	*- FS
13	1		*REAR TYRE	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett.

Sub Total (\$)	3,565.00	195.00
+ Margin on L,N Items 10.00/10.00% (\$)	336.50	19.50
Total Parts (\$)	3,901.50	214.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT /WELD REAR FENDER ,PANEL BEAT OTHER PANELS ,REMOVE & REPLACE DAMAGED PARTS	New	1,000.00	700.00
2	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS	New	100.00	30.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING	New	50.00	0.00
4	TO SPRAY PAINTING FOR RH SIDE PORTIONS & AFFECTED AREAS	New	1,000.00	500.00
5	TO DO WHEEL ALIGNMENT	New	150.00	80.00
6	TO REMOVE & TRANSFER DOOR COMPONENTS	New	150.00	0.00
7	TO DO ARTWORK COMPANY STICKER	New	750.00	300.00
Gross Labour Cost (\$)			3,200.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >