

REPAIR ESTIMATE FOR GBB465H

No.	Qty	List Items			
1	1	Rear bumper	374.45	\$ By	517.20 ✓
2	2	Rear bumper side clips		\$ Milm	60.00 ✓
3	4	Rear bumper inner bracket		\$ Di	154.00 ✓
4	1	Rear bumper inner reinforcement		\$ NIP	382.00 X
5	1 set	Rear bumper clips		\$ M	40.00 ✓
6	1	LH taillamp	366.20	\$ CM	577.20 ✓
7	1	LH taillamp lower garnish		\$ Milm	94.80 ✓
8	1	Rear tailgate	1956.20	\$ By	2,162.72 ✓
9	1	Rear tailgate centre "TOYOTA" logo		\$ M	66.20 ✓
10	1	Rear tailgate LH "TOYOTA" emblem		\$ M	24.00 ✓
11	1	Rear tailgate LH "HIACE" emblem		\$ M	39.00 ✓
12	1	Rear tailgate top lock		\$ K	289.70 X
13	1	Rear tailgate central lock		\$ K	260.10 X
14	1	Rear tailgate lower lock catch		\$ K	85.00 X
15	1	Rear tailgate weatherstrip	381.90	\$ Div/Ret	391.20 508m
16	1	Rear tailgate inner trim board		\$ S	186.70 X
17	1 set	Rear tailgate inner board clips		\$ M	50.00 X
18	1	Rear end panel inner	757068-26320	\$ By	1,104.70 ✓
19	1	Rear end panel outer		\$ A	580.10 ✓
20	1	Rear floor panel top beam	174.10	\$ B	270.70 ✓
21	1	Rear lower spare tyre carrier		\$ K	247.80 X
				\$	7,583.12
				\$	1,895.78
				\$	5,687.34
				Total :	
				\$	425.00

Special Nett Items

22	1 set	Reverse sensors		\$ M	250.00 2005m
23	1 set	Rear windscreen sealant		\$ M	80.00 405m
24	1 set	Rear end panel sealant		\$ M	80.00 305m
25	1	Rear tailgate LH "70km/h" sticker		\$ M	15.00 ✓

Total : \$ 425.00

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	1,000.00 700
2	To putty and spray Spray Paintings charges.	\$	1,000.00 700
3	To remove, refit rear windscreen glass.	\$	140.00 120
4	To check wirings and lightings.	\$	60.00 20
5	To remove, refit reverses sensors.	\$	80.00 50
6	To remove, refit rear tailgate fittings.	\$	80.00 60
7	To remove, refit rear upholstery and attachments.	\$	120.00 60
8	To supply and apply anti rust treatment	\$	90.00 60
Total :		\$	2,570.00

Total Parts and Labour : \$ 8,682.34