8/12/2021 Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG21004503/T1RS3Q2

Date:

12/08/2021

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Nature of Claim:

2070145928

Claimant Vehicle No:

SH8307X 06/04/2021 Insured Vehicle No:

SKS8880T TP

Claim No:

1744463874SG

JTDKB3FU603080935

2ZR2C22143

307877 km

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SH8307X

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

31/05/2019 (Man. Year: 2018) Reg. Date:

Colour: Blue

**Engine Capacity:** 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable):

**Engine Modification:** Yes

Pre-accident Condition: No

**CONDITION OF TYRES** 

Front Tyre Size: 195/65 R15 Rear Tyre Size: Rear Left Side:

195/65 R15

Front Left Side: Front Right Side: West Lake 6 mm West Lake 6 mm

Rear Right Side:

West Lake 6 mm West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,022.62	476.47	546.15	53.41
Miscellaneous Items		0.00	0.00	0.00	
Labour		820.00	630.00	190.00	23.17
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	1,842.62	1,106.47	736.15	39.95
	+ GST 7.00/7.00% (S\$)	128.98	77.45	51.53	39.95

787.68 **Nett Amount (S\$)** 1,971.60 1,183.92 39.95

> Global Sum Settlement (S\$) 0.00

INSPECTION

Date of Assignment: 08/04/2021

ComfortDelGro Engineering Pte Ltd (Loyang) Date Inspected: Inspected At: 08/04/2021

59 Loyang Drive Singapore 508969

Estimated Period of Repair: 2.0 days

MOHD TAUFIKH BIN HAMID Adjuster: Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	458.60 FL	*- FL
2	1		*REAR BUMPER CENTER GUARD	Deformed	552.60 FL	*552.60 FL
3	1		*REAR BUMPER TOW COVER	Deformed	82.70 FL	*82.70 FL
4	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*-FL
5	1		*REVERSE SENSOR	Not Necessary	135.70 FS	*-FS
6	1		*REAR BUMPER MAT	Not Necessary	50.00 FS	*-FS
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) - List Item Discount on L Items 25.00/25.00% (S\$)		<b>1,301.60</b> 278.98	<b>635.30</b> 158.83		
				Total Parts (S\$)	1,022.62	476.47
			Re	port was unsubmitted during this print-out.		

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No Particulars	Lab.Type	Repairer's	Amount
Labour Items			
1 PANEL BEATING	New	400.00	350.00
2 SPRAYPAINT CHARGE	New	300.00	250.00
3 R/I REVERSE SENSOR	New	120.00	30.00
	Gross Labour Cost (S\$)	820.00	630.00
	Report was unsubmitted during this print-out.		

< END OF ESTIMATES >