

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004509/URS3Q2
Date: 18/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070135893
Claimant Vehicle No :	SLP6957Z	Insured Vehicle No :	GBG6987C
Date of Loss:	27/03/2021	Nature of Claim:	TP
		Claim No:	6667190763SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP6957Z	Engine No:	3ZZ4828836
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106128614
Reg. Date:	30/01/2009 (Man. Year: 2008)	Odometer:	137292 km
Colour:	Beige		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,898.60	1,825.86	4,072.74	69.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	820.00	1,340.00	62.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,058.60	2,645.86	5,412.74	67.17
Approved Total (Overridden) (S\$)		2,100.00		

(S\$)	8,058.60	2,100.00	5,958.60	73.94
+ GST 7.00/7.00% (S\$)	564.10	147.00	417.10	73.94
Nett Amount (S\$)	8,622.70	2,247.00	6,375.70	73.94
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,434.45		

INSPECTION

Date of Assignment: 08/04/2021

Date Inspected: 14/04/2021

Inspected At:

Automobile Integrated Management Pte Ltd (HQ)
 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing)
 Singapore 415933

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Cut	561.90 FL	*481.20 FL
2	1		*FRONT BUMPER LOGO	Necessary	86.65 FL	*65.10 FL
3	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	89.95 FL	*- FL
4	1		*FRONT BUMPER TOP SEAL	Necessary	85.90 FL	*85.90 FL
5	1		*FRONT BUMPER REINFORCEMENT	Repair	441.50 FL	*- FL
6	2		*FRONT BUMPER SIDE RETAINERS -L/R	Not Necessary	87.80 FL	*- FL
7	1		*FRONT BONNET	Not Necessary	1,485.60 FL	*- FL
8	1		*FRONT BONNET LOCK	Not Necessary	121.60 FL	*- FL
9	1		*FRONT BONNET SEAL	Not Necessary	86.60 FL	*- FL
10	1		*FRONT BONNET INSULATOR	Not Necessary	211.45 FL	*- FL
11	10		*FRONT BONNET INSULATOR CLIPS	Not Necessary	55.00 FL	*- FL
12	1		*FRONT GRILLE ASSY	Cracked	331.90 FL	*288.10 FL
13	2		*FRONT HEADLAMPS -L/R	Holder Cracked	1,361.00 FL	*1,290.20 FL
14	1		*FRONT BRACE PANEL	Bent	110.65 FL	*110.65 FL
15	1		*FRONT SUPPORT PANEL	Repair	991.50 FL	*- FL
16	1		*AIR CON CONDENSER	Not Necessary	1,435.90 FL	*- FL
17	2		*HORNS	Not Necessary	179.90 FL	*- FL
18	1		*SET FRONT NO PLATE WITH HOLDER	Cut	60.00 FS	*40.00 FS
19	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,829.80	2,406.15
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,931.20	580.29
Total Parts (\$\$)	5,898.60	1,825.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK FRONT ELECTRICAL WIRING	New	80.00	20.00
2	TO REMOVE ,REFIX A/C CONDENSER & REFILL A/C GAS	New	150.00	0.00
3	TO RESPRAY UNDERCOATING	New	80.00	0.00
4	TO RESPRAY PAINTING AND ETC	New	950.00	400.00
5	PANEL BEATING ,CUT ,WELD REMOVE & REPLACING ABOVE PARTS	New	900.00	400.00
Gross Labour Cost (S\$)			2,160.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >