

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21004512/AGS3Q2
Date: 09/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0004151
Claimant Vehicle No :	SJN393Z	Insured Vehicle No :	XE1098B
Date of Loss:	06/04/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001579

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN393Z		
Make & Model:	MITSUBISHI LANCER, 2.0 L MIVEC (A)	Engine No:	4B11BS2200
Reg. Date:	30/01/2009 (Man. Year: 2008)	Chassis No:	JMYSTCY4A8U004933
Colour:	Grey	Odometer:	161478 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	6 mm	Rear Left Side:	6 mm
Front Right Side:	6 mm	Rear Right Side:	6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,621.20	6,535.71	12,085.49	64.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,640.00	2,020.00	2,620.00	56.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,261.20	8,555.71	14,705.49	63.22
Approved Total (Overridden) (S\$)		6,800.00		

(S\$)	23,261.20	6,800.00	16,461.20	70.77
+ GST 7.00/7.00% (S\$)	1,628.28	476.00	1,152.28	70.77
Nett Amount (S\$)	24,889.48	7,276.00	17,613.48	70.77
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 07/04/2021

Date Inspected: 07/04/2021

Estimated Period of Repair: 6.0 days

Inspected At: Xin Hua Workshop Pte Ltd (HQ)
23 Kaki Bukit Ave 4 #04-01
Singapore 415933

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2021)
Parts:	143	mitsubishi LANCER 2.0 L MIVEC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN393Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER SIDE RETAINER	O/S Cracked	87.90 F	*42.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
3	1		*REAR BUMPER	Torn	1,148.70 F	*815.00 FL
4	1		*TAILLAMP	Not Necessary	398.70 F	*- FL
5	1		*TAILLAMP INNER SEALER	Not Necessary	40.00 F	*- FL
6	1		*SET TAILLAMP CLIPS	Not Necessary	35.00 F	*- FL
7	1		*REAR FENDER	Repair	1,345.80 F	*- FL
8	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 F	*- FL
9	1		*REAR FENDER INNER SHIELD RH	Torn	189.70 F	*58.00 FL
10	1		*SET REAR FENDER INNER SHIELD CLIPS	Necessary	30.00 F	*10.00 FL
11	1		*REAR AIR VENT	Not Necessary	48.00 F	*- FL
12	1		*REAR RIM RH	Cut	980.40 FS	*400.00 FS
13	1		*REAR ABSORBER RH	Bent	462.00 F	*345.00 FL
14	1		*REAR UPPER ARM RH	Bent	386.90 F	*190.00 FL
15	1		*REAR LOWER ARM RH	Bent	328.60 F	*328.60 FL
16	1		*REAR CONTROL ARM RH	Bent	398.70 F	*245.00 FL
17	1		*REAR KNUCKLE ARM RH	Damaged	458.00 F	*458.00 FL
18	1		*REAR WHEEL BEARING RH	Damaged	396.00 F	*396.00 FL
19	1		*REAR WHEEL SPEED SENSOR RH	Not Necessary	245.00 F	*- FL
20	1		*REAR DOOR RH	Distorted	1,654.30 F	*1,065.00 FL
21	1		*REAR DOOR GLASS REGULATOR RH	Damaged	487.90 F	*295.00 FL
22	1		*REAR DOOR GLASS REGULATOR MOTOR RH	Not Necessary	429.70 F	*- FL
23	1		*REAR DOOR RUNCHANNEL RH	Not Necessary	298.70 F	*- FL
24	1		*REAR DOOR GLASS STICKER RH	Necessary	98.70 F	*98.70 FL
25	1		*REAR DOOR GLASS WINDOW RH	Cut	785.80 F	*224.00 FL
26	1		*REAR DOOR WEATHERSTRIP RH	Torn	298.60 F	*298.60 FL
27	2		*REAR DOOR HINGES RH	Not Necessary	137.20 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR DOOR CHECKER RH	Not Necessary	98.70 F	*- FL
29	2		*REAR DOOR INNERTRIM RH	Cracked	698.70 F	*565.00 FL
30	1		*REAR DOOR HANDLE RH	Damaged	198.70 F	*98.00 FL
31	1		*REAR DOOR HANDLE COVER RH	Not Necessary	54.80 F	*- FL
32	1		*BOOT LID TOP SPOILER	Not Necessary	450.00 FS	*- FS
33	1		*REAR BUMPER LOWER SKIRT	Not Necessary	950.00 FS	*- FS
34	1		*SET REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
35	1		*SET SOUND PROOFING (TWO LAYERS)	Necessary	750.00 FS	*350.00 FS
36	1		*SET ROCKFORD SPEAKER	Not Necessary	700.00 FS	*- FS
37	1		*REAR DOOR TINTED FILM	Necessary	480.00 FS	*180.00 FS
38	1		*SIDESKIRT RH	Cracked	980.00 FS	*600.00 FS
39	1		*REAR SKIRT RH	Not Necessary	750.00 FS	*- FS
40	1		*REAR RIM RH	Not Necessary	980.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,621.20	7,091.90
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	556.19
Total Parts (\$)	18,621.20	6,535.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,800.00	700.00
2	SPRAY PAINTING	New	1,800.00	800.00
3	CHECK WIRING ON REAR TAILAMP	New	120.00	30.00
4	TO TRANSFER REAR DOOR MECHANISM	New	180.00	40.00
5	ANTI RUST	New	180.00	80.00
6	REMOVE AND INSTALL REVERSE SENSOR	New	120.00	50.00
7	REMOVE AND INSTALL REAR DOOR GLASS	New	120.00	40.00
8	REMOVE AND INSTALL REAR UNDERCARRIAGE	New	200.00	200.00
9	TO PERFORM COMPUTERIZE WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (\$\$)			4,640.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >