

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933
Tel : 6844-1985 Fax : 6844-5185
Reg : 201838521G

VEHICLE REPAIR ESTIMATE

MAKE/MODEL MITSUBISHI LANCEX EX 2.0 GT
CHASSIS NO JMYSTCY4A8U004933
CAR PLATE NO SJN393Z
REG DATE 30.01.2009
DATE OF ACCIDENT 06.04.2021/0735

TP III
Cecilia.

LIST PRICE

1	1 pc	Rear Bumper Side Retainers RH <i>removed</i>		87.90	42
2	1 set	Rear Bumper Clips <i>new</i>		50.00	30
3	1 pc	Rear Bumper <i>torn</i>		1,148.70	815
4	1 pcs	Taillamp <i>new</i>		398.70	+
5	1 pcs	Taillamps Inner Sealer <i>new</i>		40.00	+
6	1 set	Taillamps Clips		35.00	+
7	1 pc	Rear Fender <i>Regis</i>		1,345.80	+
8	1 set	Rear Fender Inner Trim Clips <i>new</i>	30.00	60.00	+
9	1 pc	Rear Fender Inner Shield RH <i>torn</i>		189.70	58
10	1 set	Rear Fender Inner Shield Clips <i>new</i>		30.00	20
11	1 pc	Rear Air Vent <i>new</i>		48.00	+
12	1 pc	Rear Rim rh <i>cut</i>		980.40	400 (sw)
13	1 pc	Rear Absorber RH <i>Bent</i>		462.00	345
14	1 pc	Rear Upper Arm RH <i>Bent</i>		386.90	190
15	1 pc	Rear Lower Arm RH <i>Bent</i>		328.60	-
16	1 pc	Rear Control Arm RH <i>Bent</i>		398.70	245
17	1 pc	Rear Knuckle Arm RH <i>Damaged</i>		458.00	-
18	1 pc	Rear Wheel Bearing RH <i>Damaged</i>		396.00	-
19	1 pc	Rear Wheel Speed Sensor RH <i>new</i>		245.00	+
20	1 pc	Rear door RH <i>Distorted</i>		1,654.30	1065
21	1 pc	Rear door glass regulator RH <i>Damaged</i>		487.90	295
22	1 pc	Rear door glass regulator motor RH <i>new</i>		429.70	+
23	1 pc	Rear door runchannel RH <i>new</i>		298.70	+
24	1 pc	Rear door glass sticker RH <i>new</i>		98.70	+
25	1 pc	Rear door glass window RH <i>cut</i>		785.80	224
26	1 pc	Rear door weatherstrip RH <i>torn</i>		298.60	-

27	2 pc	Rear door hinges RH <i>2M</i>	68.60	137.20	+
28	1 pc	Rear door checker RH <i>1M</i>		98.70	+
29	2 pc	Rear door innertrim RH <i>cracked</i>		<u>698.70</u>	565.
30	1 pc	Rear door handle RH <i>Door</i>		198.70	✓ 98
31	1 pc	Rear door handle cover RH <i>new</i>		54.80	+

65561-9 S.N. 400

55005.71

C/F

12,331.20

Special Nett

1	1 pc	Boot Lid Top Spoiler <i>new</i>		450.00	+
1	1 pc	Rear Bumper Lower Skirt <i>new</i>		950.00	+
1	1 set	Reverse Sensor <i>new</i>		250.00	+
1	1 set	sound proofing (two layers) <i>new</i>		<u>750.00</u>	350
1	1 set	rockford speaker <i>new</i>		700.00	+
1	1	Rear door tinted film <i>new</i>		<u>480.00</u>	180.
1	1 pc	Sideskirt rh <i>cracked</i>		980.00	600.
1	1 pc	rear skirt rh <i>new</i>		750.00	+
1	1 pc	Rear Rim rh <i>new</i>		980.00	+

1130

C/F

6,290.00

Labour charge

Panel Beating		1,800.00	700
Spray painting		<u>1,800.00</u>	800
Check Wiring on rear tailamp		120.00	30
To transfer rear door mechanism		180.00	40
Anti rust		180.00	80
Remove and install reverse sensor		120.00	50
Remove and install rear door glass		120.00	40
Remove and install rear undercarriage.		200.00	✓
To perform computerize wheel alignment		<u>120.00</u>	80
subtotal		\$	<u>4,640.00</u>

Grand total

2020

23,261.20

Person Incharge: Allan

Direct Contact: +65 8782 7171

Email: xinhuaworkshop1@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 8555.71

f/s: 6.8k

06 Days