LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21004514/QTF3E2

Date: 28/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900011427

Claimant Vehicle ORDONORY

No: SBS8803Z Insured Vehicle No: SLU8471T

Date of Loss: 06/04/2021 Nature of Claim: TP Claim No: 8811392381SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBS8803Z

Make & Model: SCANIA K94IB4X2, 9.0 D (M) Engine No: 6422538

Reg. Date: 27/10/2009 (Man. Year: 2009) Chassis No: YS2K4X20001865725

Colour: Multi-colour Odometer: 999735 km

Engine Capacity: 9290 cc
Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	800.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	800.00	800.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	56.00	56.00	0.00	0.00
Nett Amount (S\$)	856.00	856.00	0.00	0.00

INSPECTION

Date Inspected:

Date of Assignment: 09/04/2021

SBS Transit Ltd (AMK)

15 Ang Mo Kio Street 63

Singapore 569117

Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN Manager: DENISE TAY KWEE CHENG

09/04/2021

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Inspected At:

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	SUPPLY 3 WORKERS (16 WORKING HOURS) }	New	800.00	800.00
2	-REPLACE LEFT SIDE PANEL NO.3&4 }	New	0.00	0.00
3	-REPAIR LEFT SIDE DOOR NO.6 }	New	0.00	0.00
4	-REPAIR RADIATOR DOOR }	New	0.00	0.00
5	-SPRAY PAINTING RADIATOR DOOR }	New	0.00	0.00
		Gross Labour Cost (S\$)	800.00	800.00
	Report was unsu	ubmitted during this print-out.		

< END OF ESTIMATES >