

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG20010640/EQF3E2-1

Date: 13/04/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001430656		
Claimant Vehicle No :	SMQ5916G	Insured Vehicle No :	SJH5281L		
Date of Loss:	01/10/2020	Nature of Claim:	TP	Claim No:	248255

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ5916G	Engine No:	D4162T2955108
Make & Model:	VOLVO S60, 1.6 D2 (A)	Chassis No:	YV1FS84ABF2337650
Reg. Date:	18/12/2014 (Man. Year: 2014)	Odometer:	95360 km
Colour:	White		
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,497.53	6,036.78	5,460.75	47.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,419.00	1,822.50	596.50	24.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,916.53	7,859.28	6,057.25	43.53
Approved Total (Overridden) (S\$)		6,250.00		
(S\$)	13,916.53	6,250.00	7,666.53	55.09
+ GST 7.00/7.00% (S\$)	974.16	437.50	536.66	55.09
Nett Amount (S\$)	14,890.69	6,687.50	8,203.19	55.09

INSPECTION

Date of Assignment:	05/10/2020		
Date Inspected:	05/10/2020	Inspected At:	Garage 13 Pte. Ltd. (HQ) 8 Kaki Bukit Avenue 4, #03-46 Premier Singapore 415875
Estimated Period of Repair:	6.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Apr 2021)
Parts:	143	VOLVO S60 1.6 D2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ5916G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair / Respray	2,454.50 FN	*- FN
2	1		*BOOT LID VOLVO LOGO	Necessary	81.50 FN	*81.50 FN
3	1		*BOOT LID EMBLEM S60	Necessary	74.10 FN	*74.10 FN
4	1		*BOOT LID EMBLEM D2	Necessary	74.10 FN	*74.10 FN
5	1		*BOOT LID LOCK	Bent	452.50 FN	*452.50 FN
6	2		*BOOT LID REFLECTOR	Intact	597.00 FN	*- FN
7	1		*REAR BUMPER	Deformed	1,598.50 FN	*1,440.00 FN
8	1		*REAR BUMPER LOWER	Crushed	612.20 FN	*486.00 FN
9	1		*REAR BUMPER REINFORCEMENT	Bent	1,409.30 FN	*1,215.00 FN
10	1		*REAR BUMPER INNER RAIL GUIDE	Damaged	274.50 FN	*274.50 FN
11	2		*REAR BUMPER SIDE BRACKET	Bent	99.80 FN	*99.80 FN
12	1		*REAR BUMPER TOW COVER	Missing	61.00 FN	*61.00 FN
13	2		*REAR BUMPER SIDE RETAINER	Necessary / Damaged	190.60 FN	*190.60 FN
14	1		*REAR BUMPER REVERSE SENSOR (4PCS)	Damaged (2Pcs Only)	964.00 FN	*482.00 FN
15	1		*REAR BUMPER REVERSE SENSOR HOLDER (4PCS)	Damaged (3Pcs Only)	143.20 FN	*107.40 FN
16	2		*TAIL LAMP	Serviceable	814.00 FN	*- FN
17	1		*REAR END PANEL	Repair	921.30 FN	*- FN
18	1		*REAR END PANEL TOP GARNISH	Deformed	293.80 FN	*293.80 FN
19	1		*BOOT LID KEYLESS SENSOR	Malfunction	346.50 FN	*346.50 FN
20	1		*REAR EXHAUST PIPE	Bent / Dented	985.40 FN	*985.40 FN
21	2		*REAR EXHAUST MOUNTING	Serviceable	64.00 FN	*- FN
22	1		*REAR EXHAUST INSULATOR	Serviceable	129.90 FN	*- FN
23	1		*REAR BUMPER CLIPS (18PCS)	Necessary	81.00 FS	*30.00 FS
24	2		*REAR END PANEL TOP GARNISH CLIP	Necessary	9.00 FS	*9.00 FS
25	1		*REAR END PANEL SEALANT	Serviceable	30.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	12,761.70	6,703.20
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	1,264.17	666.42
Total Parts (\$\$)	11,497.53	6,036.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	1,125.00	800.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / METARIAL	New	850.00	700.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	60.00	30.00
4	REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING	New	76.50	0.00
5	SPECIALIST CHARGES - DIAGNOSTIC FAULT CODE / RESET	New	150.00	150.00
6	REMOVE AND REPLACE REAR EXHAUST SYSTEM	New	90.00	90.00
7	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY)	New	22.50	22.50
8	CONDUCT WATER LEAK TEST FOR REAR PORTION ASSOCIATED REPAIR WORKS	New	45.00	30.00
Gross Labour Cost (\$\$)			2,419.00	1,822.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >