



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address   | Owner Name & Vehicle Info  |
|--|--|
| AIG Asia Pacific Insurance Pte. Ltd.<br>MOTOR CLAIM DEPARTMENT<br>78 SHENTON WAY #09-16<br>AIG BUILDING<br>SINGAPORE 079120<br>Contact No 64191000 | Cust No/Name /KOO YI XUAN MICHELLE<br>Reg No/Reg Date SMX286L*ECB20/ 22/12/202<br>Date In/Mileage / 0<br>Chassis No KNAD6811VL6456277<br>Engine No G3LCLP068357<br>Make/Model KIA/STONIC 1.0 A BET<br>Colour/Trim BEG SIGNAL RED / WK SATURN BLACK |

| Account No | Terms  | Date/Time Printed | CSE | Operator          | WIP No |
|------------|--------|-------------------|-----|-------------------|--------|
| LAX00000   | Credit | 06/04/2021/ 17:09 | QUK | 282 / Kevin Leong | 31623  |

| Description of Goods / Services  | Qty  | Unit Price | Disc% | Amount      |
|--|------|------------|-------|-------------|
| E PNT88000<br>REPLACE FRT BUMPER, FRT RH FENDER & AFFECTED AREA 400 X 1                      |      |            |       | 400 1200.00 |
| E PNT98000<br>PAINT WORK ON FRT BUMPER & FRT RH FENDER 2 X 350                               |      |            |       | 40 80.00    |
| M SUNDRY<br>PERFORM RUST PREVENTION  |      |            |       | 30.00       |
| A 54900099<br>CHECK WIRING & CHASSIS ELECTRICAL SYSTEM                                       |      |            |       | 120.00      |
| A 10028901<br>TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST<br>USING HI-SCAN PRO TEST |      |            |       | 20 50.00    |
| M SUNDRY<br>SUNDRIES   |      |            |       |             |
| M PANEL-FENDER, RH X R X MKI   | 1.00 | 401.00     | 20.00 | 320.80      |
| M INSULATOR-FENDER RH X R X MKI  | 1.00 | 27.00      | 20.00 | 21.60       |
| M COVER-FR BUMPER UPB BR   | 1.00 | 476.00     | 20.00 | 380.80      |
| M BRACKET-FR BUMPER SIDE, RH ? - BR  | 1.00 | 13.00      | 20.00 | 10.40       |
| M COVER-FR BUMPER, LWR CNT   | 1.00 | 367.00     | 20.00 | 293.60      |
| M SKID PLATE-FR BUMPER X MKI   | 1.00 | 55.00      | 20.00 | 44.00       |
| M COVER-FR BUMPER FOG LAMP, RH X MKI   | 1.00 | 64.00      | 20.00 | 51.20       |
| M GUARD ASSY-FRONT WHEEL, RH ? X MKI   | 1.00 | 56.00      | 20.00 | 44.80       |
| M ORNAMENT-KIA NO.115 X MKI  | 1.00 | 32.00      | 20.00 | 25.60       |

Estimate

Steve (LKK)  
13/4/21, 4.00pm  
OO- NM PL  
EXENS - ?  
P/P

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

|           |                      |                 |
|-----------|----------------------|-----------------|
| My Pol Sy | Nett                 | 3,372.80        |
| 4 days    | 7% GST on            | 3372.80         |
|           | <b>Total Payable</b> | <b>3,608.90</b> |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.