

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21004523/T1TF3Q2
Date: 19/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070123695
Claimant Vehicle No :	GY6484H	Insured Vehicle No :	GBK5155Y
Date of Loss:	03/04/2021	Nature of Claim:	TP
		Claim No:	1452660842SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GY6484H	Engine No:	2KD1229297
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Chassis No:	JTFHS02P100011474
Reg. Date:	23/06/2005 (Man. Year: 2005)	Odometer:	705571 km
Colour:	White		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Condor 6 mm	Rear Left Side:	Condor 6 mm
Front Right Side:	Condor 6 mm	Rear Right Side:	Condor 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

5/19/2021

Adjuster Report

Date of Assignment: 09/04/2021

Date Inspected: 09/04/2021

Inspected At:

Kwan Ying Mun Motor Service (HQ)
Blk 3023A Ubi Road 1, #01-57
Singapore 408717

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/19/2021

Adjuster Report

MARKET VALUE: \$24,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR BUMPER	Deformed	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
5	1		*REAR BUMPER LOWER BRACKET	Bent	0.00 F	*- F
6	1		*REAR END PANEL	Bent	0.00 F	*- F
7	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
8	1		*REAR LH TAILLAMP PANEL LOWER	Bent	0.00 F	*- F
9	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
10	1		*REAR RH TAILLAMP PANEL LOWER	Bent	0.00 F	*- F
11	1		*TAILGATE	Bent	0.00 F	*- F
12	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
13	1		*TAILGATE OUTER HANDLE	Deformed	0.00 F	*- F
14	1		*TAILGATE GLASS	Cracked	0.00 F	*- F
15	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
16	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
17	1		*TAILGATE LOCK	Bent	0.00 F	*- F
18	1		*TAILGATE RUBBER	Cut	0.00 F	*- F
19	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F
20	1		*SPARE TYRE BRACKET	*Check	0.00 F	*- F
21	1		*SPARE TYRE LOCK SCREW	*Check	0.00 F	*- F
22	1		*REAR EXHAUST PIPE	*Check	0.00 F	*- F
23	1		*REAR FLOOR PANEL	Repair	0.00 F	*- F
24	1		*REAR CAMERA	Distorted	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >