

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21004525/R1QF3E2

Date: 24/06/2021

REFERENCE

Insured/Claimant:	TASTY FOOD CATERING PTE LTD	Policy No:	DMCVSNW00067462003	Claim No:	SNM21D201759/C01/TANKL
Date of Loss:	28/03/2021	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG6416J	Engine No:	1KD2648453
Make & Model:	TOYOTA HIACE, 3.0 (A)	Chassis No:	KDH2010205346
Reg. Date:	19/09/2017 (Man. Year: 2016)	Odometer:	173746 km
Colour:	Grey		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$64,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Condor 6 mm	Rear Left Side:	Condor 6 mm
Front Right Side:	Condor 6 mm	Rear Right Side:	Condor 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,392.60	14,059.60	9,333.00	39.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,583.53	3,861.67	-278.14	-7.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,976.13	17,921.27	9,054.86	33.57
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	26,976.13	17,421.27	9,554.86	35.42
+ GST 7.00/7.00% (S\$)	1,888.33	1,219.49	668.84	35.42
Nett Amount (S\$)	28,864.46	18,640.76	10,223.70	35.42

INSPECTION

Date of Assignment:	09/04/2021		
Date Inspected:	09/04/2021	Inspected At:	BLK K PANDAN LOOP IND #01-12
Estimated Period of Repair:	14.0 days		Repairer: Goldbell Engineering Pte Ltd

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Jun 2021)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG6416J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		21,397.00 F	*12,064.00 F
<u>Supplementary #1</u>						
2	1		*wiper tank	Cracked	85.00 F	*85.00 F
3	1		*support panel 1015	Bent	350.00 F	*350.00 F
4	1		*wiper garnish 1311	Cracked	500.00 F	*500.00 F
5	1		*rr bumper centre clip 1007	Necessary	12.60 F	*12.60 F
6	1		*FRT DOOR GLASS OUTER MLDG 1661	Necessary	57.00 F	*57.00 F
7	1		*HOLDER CONNECTOR 1008	Cut	57.00 F	*57.00 F
8	1		*FRT BUMPER TOP BEAM 1003	Bent	93.00 F	*93.00 F
9	1		*BONNET BUSH	Necessary	10.00 F	*10.00 F
10	1		*FRT FENDER MIRROR1010	Cracked	93.00 F	*93.00 F
11	1		*STEP GARNISH CLIP 1011	Necessary	18.00 F	*18.00 F
12	1		*BONNET STAY CLIP	Necessary	6.00 F	*6.00 F
13	1		*PANEL SUB ASSY 2271	Bent	96.00 F	*96.00 F
14	1		*FAN COWLING 7767	Cracked	132.00 F	*132.00 F
15	1		*FRT SUP/BRKT LH 1013	Bent	54.00 F	*54.00 F
16	1		*FRT DASH PANEL REINF 1320	Bent	198.00 F	*198.00 F
17	1		*FRT DOOR INNER LOCK 1577	Bent	216.00 F	*216.00 F
18	1		*WIPER GARNISH COVER LH 1014	Deformed	18.00 F	*18.00 F

F=Franchise part.

Total Parts (S\$)	23,392.60	14,059.60
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOTAL LABOUR	New	1,873.20	2,032.80
2	TOTAL PAINT	New	1,580.33	1,598.87
3	ADDITIONAL	New	130.00	230.00
Gross Labour Cost (\$)			3,583.53	3,861.67

Report was unsubmitted during this print-out.

< END OF ESTIMATES >