

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG21004527/KTF3E2  
**Date:** 25/05/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993741  
**Claimant Vehicle No :** SMU4713K **Insured Vehicle No :** SKN8847S  
Date of Loss: 07/04/2021 Nature of Claim: TP Claim No: 1713801588SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU4713K**  
Make & Model: HONDA VEZEL, 1.5 (A) Engine No: LEB6743534  
Reg. Date: 14/08/2020 (Man. Year: 2018) Chassis No: RU31323523  
Colour: Metallic Red Odometer: 12316 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18  
Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9 mm  
Front Right Side: Michelin 9 mm Rear Right Side: Michelin 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,291.28	5,323.20	5,968.08	52.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	1,220.00	2,480.00	67.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,991.28</b>	<b>6,543.20</b>	<b>8,448.08</b>	<b>56.35</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,200.00</b>		
<b>(S\$)</b>	14,991.28	5,200.00	9,791.28	65.31
<b>Nett Amount (S\$)</b>	<b>16,040.67</b>	<b>5,564.00</b>	<b>10,476.67</b>	<b>65.31</b>

### INSPECTION

Date of Assignment: 09/04/2021  
Date Inspected: 09/04/2021 Inspected At: S Three Automotive & Recovery Pte Ltd - Sin Ming (HQ)  
BLK 8 SIN MING IND EST #01-64/66  
Singapore 575643  
Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	927.50 FL	*801.70 FL
2	1		*FRONT BUMPER LOWER GARNISH	Dented	300.70 FL	*300.70 FL
3	1		*FRONT BUMPER RETAINER LH	Distorted	38.00 FL	*38.00 FL
4	1		*FRONT BUMPER RETAINER RH	Serviceable	38.00 FL	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	Cracked	180.00 FL	*167.00 FL
6	1		*FRONT BUMPER TOWING COVER	Serviceable	38.00 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	321.00 FL	*321.00 FL
8	1		*FRONT HEADLAMP RH	Serviceable	1,716.70 FL	*- FL
9	1		*FRONT HEADLAMP LH	Mtg Cracked	1,716.70 FL	*1,716.70 FL
10	1		*FRONT HEADLAMP LOWER BRACKET LH	Cracked	70.00 FL	*35.00 FL
11	1		*FRONT HEADLAMP LOWER BRACKET RH	Serviceable	70.00 FL	*- FL
12	1		*FRONT HEADLAMP TOP RH	Repair	168.00 FL	*- FL
13	1		*FRONT HEADLAMP TOP LH	Repair	168.00 FL	*- FL
14	1		*FRONT CHROME	No such part	108.00 FL	*- FL
15	1		*FRONT GRILLE LOGO	Necessary	128.00 FL	*55.00 FL
16	1		*FRONT GRILLE TOP COVER	Mtg Cracked	250.00 FL	*105.00 FL
17	1		*FRONT RADIATOR GRILLE	Cracked	285.00 FL	*285.00 FL
18	1		*FRONT SIDE EMBLEM HYBRID RH	Serviceable	68.00 FL	*- FL
19	1		*FRONT SIDE EMBLEM HYBRID LH	Serviceable	68.00 FL	*- FL
20	1		*FRONT FOG LAMP RH	Serviceable	327.70 FL	*- FL
21	1		*FRONT FOG LAMP LH	Cracked	327.70 FL	*327.70 FL
22	1		*FRONT FOG LAMP COVER RH	Serviceable	85.00 FL	*- FL
23	1		*FRONT FOG LAMP COVER LH	Dented	85.00 FL	*85.00 FL
24	1		*FRONT FENDER RH	Repair	580.00 FL	*- FL
25	1		*FRONT FENDER LH	Repair	580.00 FL	*- FL
26	1		*FRONT FENDER WHEEL ARCH PROTECTOR RH	Mtg Cracked	156.20 FL	*156.20 FL
27	1		*FRONT FENDER WHEEL ARCH PROTECTOR LH	Mtg Cracked	156.20 FL	*156.20 FL
28	1		*FRONT FENDER INNER SHIELD RH	Serviceable	130.10 FL	*- FL
29	1		*FRONT FENDER INNER SHIELD LH	Serviceable	130.10 FL	*- FL
30	1		*HORN HIGH	Serviceable	40.10 FL	*- FL
31	1		*HORN LOWER	Serviceable	40.10 FL	*- FL
32	1		*RADAR SENSOR ASSY	Shorted / Dented	880.00 FL	*880.00 FL
33	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*50.00 FS
34	1		*FRONT FENDER INNER SHIELD CLIPS LH & RH	Not Necessary	100.00 FS	*- FS
35	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
36	1		*FRONT BUMPER LOWER SPOILER	Cracked	1,600.00 FS	*550.00 FS
37	1		*FRONT BUMPER LOWER SPOILER SEALANT	Serviceable	80.00 FS	*- FS
38	1		*FRONT FENDER WHEEL ARCH PROTECTOR CLIPS	Not Necessary	100.00 FS	*- FS
39	1		*FRONT NUMBER PLATE (LASER 3D)	Cracked	180.00 FS	*60.00 FS
40	1		*SET FRONT PORTION BLACK STICKER	Necessary	800.00 FS	*80.00 FS
41	1		*RADIATOR SIDE GARNISH LH	Cracked	68.30 FL	*68.30 FL
42	1		*ENGINE LOWER COVER LH	Cracked	168.00 FL	*168.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>13,374.10</b>	<b>6,456.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	2,082.82	1,133.30
<b>Total Parts (\$\$)</b>	<b>11,291.28</b>	<b>5,323.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	New	1,400.00	500.00
2	SPRAY PAINTING ON ACCIDENT AREAS	New	1,400.00	600.00
3	CHECK & REPAIR WIRING SYSTEM	New	120.00	20.00
4	RESPRAY TUFF KOTE ON AFFECTED AREAS	New	100.00	0.00
5	PROGRAMME RADAR COLLISION CODING	New	680.00	100.00
			<b>Gross Labour Cost (\$)</b>	<b>3,700.00</b>
				<b>1,220.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >