

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 1061G

| Qty | Description of Parts                                    | Condition               | Estimate By<br>Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-------------------------|-------------------------------|-------------------|
|     | REPLACEMENT OF PARTS                                    |                         |                               |                   |
| 1   | FRONT BUMPER  | DISTORTED               | 685.00                        | 685.00            |
| 1   | FRONT BUMPER BRACKET RH                                 | BENT                    | 180.50                        | 180.50            |
| 1   | FRONT BUMPER SIDE COVER RH                              | DEFORMED                | 38.00                         | 38.00             |
| 1   | FRONT RH CORNER PANEL                                   | DEFORMED                | 286.50                        | 286.50            |
| 1   | HEADLAMP RH   | CUT                     | 442.00                        | 442.00            |
| 1   | FRONT RH SIGNAL LAMP                                    | CUT                     | 325.00                        | 325.00            |
| 1   | FRONT RH WING MIRROR                                    | DAMAGED                 | 116.20                        | 116.20            |
| 1   | FRONT RH WING MIRROR STAY                               | BENT                    | 265.40                        | 265.40            |
| 1   | FRONT RH DOOR   | TO REPAIR SEE<br>LABOUR | 1,265.50                      | -                 |
| 1   | FRONT RH DOOR WEATHERSTRIPE                             | CUT                     | 126.40                        | 126.40            |
| 2   | FRONT RH DOOR HINGE @\$96.00                            | NOT NECESSARY           | 192.00                        | -                 |
| 1   | FRONT RH DOOR SIGNAL LAMP                               | MISSING                 | 98.30                         | 98.30             |
| 1   | FRONT RH STEP GARNISH                                   | CUT                     | 126.90                        | 126.90            |
| 1   | FRONT RH STEP GARNISH REFLECTOR                         | NOT NECESSARY           | 24.40                         | -                 |
|     | LESS 15% DISCOUNT                                       |                         | -                             | -403.53           |
|     |   |                         | 4,172.10                      | 2,286.67          |
|     | SPECIAL NETT ITEMS                                      |                         |                               |                   |
| 1   | FRONT NUMBER PLATE (SN)                                 | DEFORMED                | 30.00                         | 30.00             |
| 1   | FRONT NUMBER PLATE HOLDER (SN)                          | DEFORMED                | 30.00                         | 30.00             |
| 1   | FRONT RH DOOR OUTER PROTECTOR (SN)                      | CUT                     | 100.00                        | 80.00             |
|     |   |                         | 160.00                        | 140.00            |
|     | <u>LABOUR</u>   |                         |                               |                   |
|     | PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT RH DOOR. |                         | 1,200.00                      | 700.00            |
|     | SPRAY PAINTING.   |                         | 1,200.00                      | 600.00            |
|     | WIRING.   |                         | 50.00                         | 30.00             |
|     | TO TRANSFER DOOR FITTINGS.                              | NOT NECESSARY           | 150.00                        | -                 |
|     |   |                         | 2,600.00                      | 1,330.00          |
|     | GRAND TOTAL   |                         | 6,932.10                      | 3,756.67          |

Report Ref No. CS/AGI21004531/Aqf3n2



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS |  | 3,000.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION)      |  |          |

Report Ref No. CS/AGI21004531/Aqf3n2



**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.