

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:**

CC4/AIG21004533/UPS3Q2

**Date:**

27/06/2021

**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100449319

**Claimant Vehicle No :** SMR4600T**Insured Vehicle No :**

SKZ4848C

Date of Loss: 03/04/2021

Nature of Claim:

TP

Claim No:

6591098312SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMR4600T**

Make &amp; Model: HYUNDAI AVANTE, 1.6 (A)

Engine No:

G4FGKU173007

Reg. Date: 08/01/2020 (Man. Year: 2019)

Chassis No:

KMHD841CMKU935740

Colour: Red

Odometer:

134991 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Falken 6 mm

Rear Left Side:

Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side:

Falken 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

|                                          | Repairer's      | Adjuster's      | Difference      | Diff %       |
|------------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                                    | 5,284.64        | 3,762.56        | 1,522.08        | 28.80        |
| Miscellaneous Items                      | 0.00            | 0.00            | 0.00            |              |
| Labour                                   | 2,120.00        | 1,240.00        | 880.00          | 41.51        |
| Paintwork Labour                         | 0.00            | 0.00            | 0.00            |              |
| Towing                                   | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>7,404.64</b> | <b>5,002.56</b> | <b>2,402.08</b> | <b>32.44</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                 | <b>4,000.00</b> |                 |              |

|                                                 |                 |                 |                 |              |
|-------------------------------------------------|-----------------|-----------------|-----------------|--------------|
| (S\$)                                           | 7,404.64        | 4,000.00        | 3,404.64        | 45.98        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 518.32          | 280.00          | 238.32          | 45.98        |
| <b>Nett Amount (S\$)</b>                        | <b>7,922.96</b> | <b>4,280.00</b> | <b>3,642.96</b> | <b>45.98</b> |
| <b>+ Car Rental (6.0 x S\$100.00/day) (S\$)</b> |                 | 600.00          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                 | 2.00            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>4,882.00</b> |                 |              |
| <b>Global Sum Settlement (S\$)</b>              |                 | <b>4,800.00</b> |                 |              |

INSPECTION

Date of Assignment: 09/04/2021

Date Inspected: 09/04/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Focus Auto Pte Ltd (HQ)  
 1 Kaki Bukit Ave 6, #02-48/50 Autobay  
 Singapore 417883

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition     | Repairer's  | Amount     |
|-----|-----|----------|---------------------------------------|---------------|-------------|------------|
| 1   | 1   |          | *FRONT FENDER RH                      | Badly Dented  | 396.70 FL   | *396.70 FL |
| 2   | 1   |          | *FRONT FENDER DUCT COVER -RH          | Serviceable   | 83.30 FL    | *- FL      |
| 3   | 6   |          | *FRONT FENDER DUST COVER CLIPSE -RH   | Not Necessary | 33.00 FL    | *- FL      |
| 4   | 1   |          | *FRONT FENDER LAMP -RH                | Not Necessary | 48.20 FL    | *- FL      |
| 5   | 1   |          | *FRONT HEADLAMPS -RH                  | Cracked       | 586.20 FL   | *586.20 FL |
| 6   | 1   |          | *FRONT BUMPER                         | Distorted     | 498.60 FL   | *465.00 FL |
| 7   | 1   |          | *FRONT BUMPER SITE RETAINER -RH       | Bent          | 20.70 FL    | *20.70 FL  |
| 8   | 1   |          | *FRONT BUMPER LAMP -RH                | Cracked       | 89.20 FL    | *89.20 FL  |
| 9   | 1   |          | *FRONT BUMPER LAMP INNER SUPPORT -RH  | Cracked       | 62.40 FL    | *62.40 FL  |
| 10  | 1   |          | *FRONT BUMPER INNER SIDE AIR DUCT -RH | Serviceable   | 58.20 FL    | *- FL      |
| 11  | 1   |          | *FRONT SHOCK ABSORBER                 | N/S Bent      | 597.20 FL   | *298.60 FL |
| 12  | 2   |          | *FRONT KNUCKLE                        | Bent          | 653.60 FL   | *653.60 FL |
| 13  | 2   |          | *FRONT HUB BEARING                    | Damaged       | 440.40 FL   | *440.40 FL |
| 14  | 2   |          | *FRONT LOWER ARM                      | Bent          | 690.40 FL   | *690.40 FL |
| 15  | 1   |          | *FRONT WASHER TANK                    | Not Necessary | 160.20 FL   | *- FL      |
| 16  | 2   |          | *FRONT SPORT RIM                      | Cut / Bent    | 1,500.00 FS | *800.00 FS |
| 17  | 1   |          | *FRONT TYRE -LH                       | Serviceable   | 250.00 FS   | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                 |                 |
|----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>6,168.30</b> | <b>4,503.20</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$)</b> | 883.66          | 740.64          |
| <b>Total Parts (\$)</b>                                  | <b>5,284.64</b> | <b>3,762.56</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                              | Lab.Type | Repairer's      | Amount          |
|---------------------------------|------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                          |          |                 |                 |
| 1                               | PANEL BEATING                            | New      | 850.00          | 300.00          |
| 2                               | CHECK WIRING                             | New      | 60.00           | 20.00           |
| 3                               | RUST PROOFING                            | New      | 60.00           | 30.00           |
| 4                               | TO REMOVE & REPLACE FRONT UNDER CARRIAGE | New      | 350.00          | 240.00          |
| 5                               | TO ADJUST ALIGNMENT                      | New      | 50.00           | 50.00           |
| 6                               | TO SPRAY PAINT                           | New      | 750.00          | 600.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                          |          | <b>2,120.00</b> | <b>1,240.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >