

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |   |                 |                        |
|---|--|---|-----------------|------------------------|
|   | AXA INSURANCE  | PTE LTD   | Ref:            | CC4/ASM21004536/Aga3q2 |
|   | 8 SHENTON WAY<br>AXA TOWERSING   |   | Date:           | 09/12/2021             |
|   | ATTN:KHOR SAW  | THENG   | Code:           | ASM                    |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM  |   |                 |                        |
|   | Insured Veh.   | SKZ 1976K   | Veh. Inspected  | SMR 9562L              |
|   | Policy No.   | GA514031  | Coverage (\$)   | 0.00                   |
|   | Claim No.  | S1M037JZ  | Excess (\$)     | 0.00                   |
|   | Assign From  |   | Assign Date     | 09/04/2021             |
| 2. Vehicle Particulars & Condition                                |  |   |                 |                        |
|   | Make & Model   | B.M.W. 216I   | c.c             | 1499                   |
|   | Engine No.   | HIDDEN  | Year of Reg.    | 2020                   |
|   | Chassis No.  | WBA6V120705P68735   | Colour          | WHITE                  |
|   | Odometer   | 115164 KM   | Steering        | IN ORDER               |
|   | Brakes   | IN ORDER  | Modification    | SPORTS RIM             |
|   | General  | GOOD  |                 |                        |
| 3. Conditions of Tyres  |  |   |                 |                        |
|   |  | Size  | Make            | Balance                |
|   | R/H Front Tyre   | 205/60 R16  | GOODYEAR        | 6 mm                   |
|   | L/H Front Tyre   | 205/60 R16  | GOODYEAR        | 6 mm                   |
|   | R/H Rear Tyre  | 205/60 R16  | GOODYEAR        | 6 mm                   |
|   | L/H Rear Tyre  | 205/60 R16  | GOODYEAR        | 6 mm                   |
| 4.  | Description of Damages   |   |                 |                        |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.   |   |                 |                        |
|   | DAMAGES SEE DETAILS.   |   |                 |                        |
| 5.  | General Information  |   |                 |                        |
|   | Accident Date  | 05/04/2021  | Inspection Date | 09/04/2021             |
|   | Survey held at   | rvey held at XIN HUA WORKSHOP PTE LTD                       |                 |                        |
|   |  | 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933 |                 |                        |
|   |  |   |                 |                        |
| 5a.   | Remarks  |   |                 |                        |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                 |                        |
| 5b.   | Estimate Days of Repair  |   |                 |                        |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days   |   |                 |                        |
|   |  |   |                 |                        |