



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 927R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BENT	569.69	569.69
1	FRONT BUMPER COVER,RH	DEFORMED	307.97	307.97
1	FRONT HEADLAMP,RH	BROKEN	569.63	471.00
1	FRONT SIGNAL LAMP,RH	BROKEN	317.10	317.10
1	FRONT HEADLAMP COVER,RH	CRACKED	276.19	276.19
1	FRONT DOOR,RH	BENT	2,071.55	1,800.00
1	FRONT CORNER PANEL,RH	SCRATCHED	505.14	346.00
1	COOLANT RETURN PIPE	BENT	235.78	235.78
	LESS 25% DISCOUNT		-1,213.26	-1,080.93
			3,639.79	3,242.80
	<u>SPECIAL NETT ITEMS</u>			
1	COMPANY LOGO STICKER (SN)	NECESSARY	360.00	200.00
			360.00	200.00
	<u>LABOUR</u>			
	REMOVE & RENEW FRONT BUMPER,BUMPER COVER,HEADLAMP,SIGNAL LAMP,CORNER PANEL & FRONT DOOR.		600.00	550.00
	REMOVE & RENEW COOLANT RETURN PIPE.		120.00	60.00
	TRANSFER PARTS.		120.00	60.00
	SPRAY PAINT FRONT DOOR,FRONT BUMPER & CORNER PANEL.		550.00	500.00
			1,390.00	1,170.00
	GRAND TOTAL		5,389.79	4,612.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,700.00

Report Ref No. CS/SMR21004544/R1uf3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.