

TP AXA
Xiao Chen.

SLM4051R .2017 March.

Perodua Bezza 1329cc

PM2B30LS003047205

Rear Bumper Distorted	658 ✓
Rear Bumper Clips. New	30(SN) ✓
Rear Bumper Side Holder x 2 ^{LH} Damaged	45 x 2 = 90 45
Rear Bumper Lower Spoiler ^{Del}	1000(SN) 700(SN)
Rear Bumper Lower Spoiler Reflector LH. ^{Cracked}	45. ✓
Reverse Sensor Damaged	280(SN) 200(SN)
Rear End Panel Dented	458 ✓
Rear End Panel Top Garnish. ^{Del}	128 ✓
Rear End Panel Top Garnish Clips. ^{new}	20(SN) ✓
Rear End Panel Sealant New	60(SN) ✓
Taillamp LH Cracked	351 ✓
Taillamp Panel LH. Buckled	210 ✓
Bootlid Dented	865 ✓
Bootlid Lock ^{XH New}	240 X
Bootlid Weatherstripe at	128 ✓

SLM4051R

Bootlid Hinge x 02 LH Bent 95
~~95 x 2 = 190~~

Bootlid Outer Chrome Moulding ^{x4} 220 x

Bootlid Antenna Sensor ^{x1} 115 x

Bezza Working. } 65 ✓
VVTi Emblem. } ^{Nec} 48 ✓

Rear LH Fender. Buckled ~~980~~ 890

Rear LH Fender Air Vent. ^{x4} 68 x

Rear LH Fender Inner Trim ^{x4} 295 x

Rear LH Fender Inner Trim Clips. ^{x4} 20. x

Rear Windscreen Moulding } 115 ✓
Rear Windscreen Sealant } ^{Nec} 60(SW). ✓

hist: 4121.

SIN: 1070

Len 10%: 3708.90

SLM40SIR.

Panel Beating,

Spray Painting,

Wiring.

To remove upholstery,

To remove rear windscreen.

To remove reverse sensor

To remove rear camera.

To remove fuel tank

To spray tuff coat.

~~1600~~ 1200

~~1500~~ 1100

~~100~~ 30

~~150~~ 60

~~180~~ 120

~~100~~ 50

~~100~~ 50

~~150~~ 80 2770

~~150~~ 80.

Total: 7548.90

L/s: 6K.

09 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: