



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 9600S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT BUMPER COVER	TORN	430.90	430.90
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT BUMPER MOULDING CENTRE UPPER	CUT	368.50	368.50
1	FRT BUMPER BRACKET TOP LH	NOT NECESSARY	28.00	-
1	FRT BUMPER SIDE BRACKET RH	NOT NECESSARY	24.00	-
1	DAY LIGHT LH	NOT NECESSARY	642.50	-
1	HEADLAMP ASSY LH	CUT	1,993.65	1,993.65
1	FRT RADIATOR GRILLE	CRACKED	1,480.00	1,480.00
	LESS 20% DISCOUNT		-997.91	-859.01
			3,991.64	3,436.04
<u>NETT ITEMS</u>				
1	FRONT NUMBER PLATE (N)	CRACKED	25.00	25.00
	LESS 10% DISCOUNT		-	-2.50
			25.00	22.50
<u>LABOUR</u>				
	PANEL BEATING.		600.00	350.00
	SPRAY PAINTING CHARGE.		500.00	250.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.	NOT NECESSARY	50.00	-
			1,200.00	630.00
GRAND TOTAL			5,216.64	4,088.54
RECOMMENDED COST OF REPAIRS (CONFIRMED)				4,088.54

Report Ref No. NS/INC21004551/T1vcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.