

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004554/APS3Q2
Date: 12/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700067565
Claimant Vehicle No :	PC2976R	Insured Vehicle No :	SQ3238Y
Date of Loss:	08/04/2021	Nature of Claim:	TP
		Claim No:	1450926332SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC2976R		
Make & Model:	TOYOTA HIACE, 3.0 COMMUTER GL (A)	Engine No:	1KD2407696
Reg. Date:	21/08/2014 (Man. Year: 2014)	Chassis No:	KDH2230020097
Colour:	Silver	Odometer:	473825 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,993.70	5,881.57	10,112.13	63.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,350.00	2,130.00	3,220.00	60.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,343.70	8,011.57	13,332.13	62.46
Approved Total (Overridden) (S\$)		6,400.00		

Nett Amount (S\$)	21,343.70	6,400.00	14,943.70	70.01
+ Car Rental (9.0 x S\$160.00/day) (S\$)		1,440.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		7,876.45		
Global Sum Settlement (S\$)		7,870.00		

INSPECTION

Date of Assignment: 09/04/2021

Date Inspected: 09/04/2021

Estimated Period of Repair: 9.0 days

Inspected At:

Smartone Auto Pte Ltd (HQ)
 8 Kaki Bukit Avenue 4, #08-09 Premier @ Kaki Bukit
 Singapore 415875

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*TAIL LAMP	Cut	780.00 FL	*780.00 FL
2	2		*TAILLAMP LOWER GARNISH	Repair	334.00 FL	*- FL
3	2		*TAILLAMP LOWER GARNISH RETAINER	Not Necessary	130.00 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER	Necessary	110.00 FL	*110.00 FL
5	4		*REAR BUMPER BRACKET	Bent	84.80 FL	*84.80 FL
6	1		*TAILGATE	Distorted	2,054.30 FL	*1,925.00 FL
7	1		*TAILGATE LOGO	Necessary	75.20 FL	*75.20 FL
8	1		*TAILGATE EMBLEM HIACE	Necessary	59.00 FL	*59.00 FL
9	1		*TAILGATE EMBLEM GL	Necessary	69.20 FL	*69.20 FL
10	1		*TAILGATE CENTER MOULDING (CHROME)	Cracked	674.80 FL	*386.00 FL
11	1		*TAILGATE LOCK OUTER HANDLE	Not Necessary	465.10 FL	*- FL
12	1		*TAILGATE STOPPER	Not Necessary	28.00 FL	*- FL
13	1		*TAILGATE INNER TRIM	Cracked	271.80 FL	*271.80 FL
14	1		*TAILGATE WEATHERSTRIP	Cut	395.00 FL	*395.00 FL
15	1		*TAILGATE WEATHERSTRIP PROTECTOR	Cracked	485.20 FL	*278.00 FL
16	1		*TAILGATE INNER LOCK	Damaged	475.60 FL	*289.00 FL
17	1		*TAILGATE LOWER LOCK	Not Necessary	45.20 FL	*- FL
18	2		*TAILGATE DAMPER	Not Necessary	254.80 FL	*- FL
19	2		*TAILGATE LOWER CORNER GARNISH	Not Necessary	39.20 FL	*- FL
20	1		*TAILGATE KEY LOCK	Not Necessary	294.70 FL	*- FL
21	1		*REAR END PANEL (INNER)	Repair	1,043.20 FL	*- FL
22	1		*REAR END PANEL (OUTER)	Dented	597.00 FL	*597.00 FL
23	1		*REAR END PANEL (EXTEND) RH	Dented	362.10 FL	*362.10 FL
24	1		*REAR FLOOR PANEL	Repair	1,888.90 FL	*- FL
25	1		*REAR SPARE TYRE BRACKET	Not Necessary	398.70 FL	*- FL
26	1		*REAR SPARE TYRE BOLT	Not Necessary	104.20 FL	*- FL
27	1		*REAR EXHAUST PIPE	Not Necessary	874.20 FL	*- FL
28	1		*REAR EXHAUST GASKET	Not Necessary	57.80 FL	*- FL
29	1		*REAR EXHAUST MOUNTING	Not Necessary	28.10 FL	*- FL
30	1		*REAR FLOOR PANELMAT	Not Necessary	1,591.50 FL	*- FL
31	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
32	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
33	1		*REAR BUMPER (SPECIAL TYPE)	Distorted	2,400.00 FS	*1,000.00 FS
34	1		*SET REAR BUMPER REFLECTOR (SPECIAL TYPE)	Cracked	380.00 FS	*120.00 FS
35	1		*REAR BUMPER A-STAR EMBLEM (SPECIAL TYPE)	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SET TAIL LAMP CLIP	Necessary	60.00 FS	*20.00 FS
37	1		*SET TAILLAMP LOWER GARNISH CLIP	Not Necessary	40.00 FS	*- FS
38	1		*SET TAILGATE CENTER MOULDING (CHROME) CLIP	Necessary	60.00 FS	*20.00 FS
39	1		*SET TAILGATE LOWER CORNER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
40	1		*SET TAILGATE INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
41	1		*TAILGATE STICKER 80/90 LEBUHRAYA KM/J (SPECIAL TYPE)	Necessary	80.00 FS	*30.00 FS
42	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
43	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*40.00 FS
44	1		*TAILGATE STICKER 70KM/H	Necessary	30.00 FS	*10.00 FS
45	1		*TAILGATE STICKER EMERGRNCY EXIT	Necessary	60.00 FS	*20.00 FS
46	1		*REAR END PANEL (INNER) SEALANT	Not Necessary	150.00 FS	*- FS
47	1		*REAR END PANEL (OUTER) SEALANT	Necessary	150.00 FS	*60.00 FS
48	1		*REAR END PANEL (EXTEND) SEALANT	Not Necessary	150.00 FS	*- FS
49	1		*REAR FLOOR PANEL SEALANT	Not Necessary	350.00 FS	*- FS
50	1		*REAR SPARE TYRE	Not Necessary	350.00 FS	*- FS
51	1		*SET REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
52	1		*REVERSE CAMERA	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	19,511.60	7,302.10
- List Item Discount on L Items 25.00/25.00% (\$)	3,517.90	1,420.53
Total Parts (\$)	15,993.70	5,881.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING AND REPLACE PARTS	New	1,800.00	1,000.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	800.00
3	WIRING BULB CHECKING	New	180.00	30.00
4	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
5	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
6	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
7	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
8	REAR CHASSIS ALIGNMENT	New	250.00	0.00
9	REMOVE AND REFIX REAR REVERSE CAMERA	New	80.00	50.00
10	REMOVE AND REFIX REVERSE SENSOR	New	80.00	50.00
11	REMOVE AND REFIX LINING & SEATS	New	480.00	0.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			5,350.00	2,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >