

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG21004555/UPA3Q2

Date:

27/09/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800048526

Claimant Vehicle No : SGM6819P**Insured Vehicle No :**

SFB3280G

Date of Loss: 05/04/2021

Nature of Claim:

TP

Claim No:

8410984455SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGM6819P**

Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)

Engine No: P520353174

Reg. Date: 29/04/2016 (Man. Year: 2016)

Chassis No: JM6BM42A8G0335643

Colour: Grey

Odometer: 366065 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: Tourador 6 mm

Rear Left Side:

Tourador 6 mm

Front Right Side: Tourador 6 mm

Rear Right Side:

Tourador 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	841.04	0.00	841.04	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	400.00	650.00	61.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,891.04	400.00	1,491.04	78.85
+ GST 7.00/7.00% (S\$)	132.37	28.00	104.37	78.85

Nett Amount (S\$)	2,023.41	428.00	1,595.41	78.85
+ Loss of Use (1.0 x S\$60.00/day) (S\$)		60.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		496.00		
Global Sum Settlement (S\$)		500.00		

INSPECTION

Date of Assignment: 09/04/2021

Date Inspected: 23/04/2021

Estimated Period of Repair: 1.0 days

Inspected At: Precise Auto Service (HQ)
No 1 Kaki Bukit Ave 6, #02-34/36
Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	Repair	958.10 FL	*- FL
2	1		*FRONT BUMPER SIDE RETAINER -RH	Not Necessary	18.70 FL	*- FL
3	1		*FRONT BUMPER SIDE ATTACHMENT -RH	Not Necessary	28.10 FL	*- FL
4	1		*FOG LAMP COVER -RH (CUT)	Not Consistent With The Impact	46.40 FL	*- FL
					Sub Total (\$\$)	1,051.30 0.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	210.26 0.00
					Total Parts (\$\$)	841.04 0.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RESPRAY AFFECTED AREAS	New	550.00	200.00
2	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR & ALIGNED ALL PARTS	New	500.00	200.00
Gross Labour Cost (S\$)			1,050.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >