

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA2495S
 Make : HYUNDAI
 Model : IONIQ(G2)

Date: 07/04/21
 Insurance: NTUC
 MVA: JUMANI

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			Rp \$459.40
10	REAR BUMPER CLIPS			ny x \$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			de - \$451.25
1	REAR LICENCE PLATE LAMP LH			x \$85.30
1	REAR LICENCE PLATE LAMP RH			x \$85.30
1	REAR BUMPER LOWER CTR MOULDING			x \$155.00
1	REAR BUMPER FOG LAMP			x \$201.50
1	REAR BUMPER TOWING COVER			x \$98.80
			451.25	
	SUB TOTAL			\$1,558.55
	LESS 20%		361	\$311.71
	DISCOUNTED TOTAL			\$1,246.84
1	REAR NUMBER PLATE		205	one \$25.00
1	REAR BUMPER REVERSE SENSOR		184.50	ms \$180.00
				\$205.00
	Labour Charge			
	PANEL BEATING			\$350.00
	SPRAY PAINTING CHARGE			250 \$300.00
	WIRING CHARGE			mm x \$50.00
	REMOVE/REFIX REVERSE SENSOR			50 \$120.00
			630	
	TOTAL LABOUR			\$820.00
	ESTIMATE TOTAL		1175.50	
			4/5 950	\$2,271.84
			2 days #	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 2789 5747
 7/4/21 @ 430
 2 days 4/5 Resurvey after repair
 Tanpin @ the auto center