



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4163L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER COVER	DEFORMED	459.40	459.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING ASSY	DEFORMED	451.25	451.25
1	REAR LICENCE PLATE LAMP LH	NOT NECESSARY	85.30	-
1	REAR LICENCE PLATE LAMP RH	NOT NECESSARY	85.30	-
1	REAR BUMPER LOWER CTR MOULDING	DEFORMED	155.00	155.00
1	REAR BUMPER FOG LAMP	NOT NECESSARY	201.50	-
1	REAR BUMPER TOWING COVER	NOT NECESSARY	98.80	-
	LESS 20% DISCOUNT		-311.71	-217.53
			1,246.84	870.12
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	MISSING	25.00	25.00
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	180.00	-
			205.00	25.00
<u>LABOUR</u>				
	PANEL BEATING.		500.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX REVERSE SENSOR.		120.00	30.00
			970.00	630.00
GRAND TOTAL			2,421.84	1,525.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,200.00

Report Ref No. NS/INC21004557/T1tcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.