

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21004560/EGS3Q2
Date: 10/01/2022**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SJL552S	Insured Vehicle No :	SLU6519D
Date of Loss:	08/04/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001545

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL552S		
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Engine No:	1ZZ3150831
Reg. Date:	13/11/2008 (Man. Year: 2008)	Chassis No:	JTDER12W503000898
Colour:	Grey	Odometer:	224314 km
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 4 mm	Rear Left Side:	West Lake 4 mm
Front Right Side:	West Lake 4 mm	Rear Right Side:	West Lake 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,921.33	1,162.56	758.77	39.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	860.00	590.00	40.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,371.33	2,022.56	1,348.77	40.01
Approved Total (Overridden) (S\$)		1,600.00		

Nett Amount (S\$)	3,371.33	1,600.00	1,771.33	52.54
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 09/04/2021

Date Inspected: 12/04/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Xinya Auto Services Pte Ltd (HQ)
Blk 1002, #01-75, Bukit Merah Lane 3
Singapore 159719

Adjuster: CHEN TSUE YEE

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL552S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	986.70 FL	*- FL
2	1		*FRONT BUMPER RETAINER	Broken	59.30 FL	*59.30 FL
3	10		*FRONT BUMPER CLIPS	Necessary	55.00 FL	*30.00 FL
4	1		*HEADLAMP	Cut	849.31 FL	*849.31 FL
5	1		*FRONT FENDER LH	Dented	611.47 FL	*611.47 FL
					Sub Total (\$\$)	2,561.78
					- List Item Discount on L Items 25.00/25.00% (\$\$)	640.45
					Total Parts (\$\$)	1,921.33
						1,162.56

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REPLACE FRONT BUMPER ,HEADLAMP,FENDER AND TO PANEL BEAT & ALIGN	New	800.00	400.00
2	TO PUTTY & SPRAY PAINT FRONT BUMPER ,FENDER AND OTHER AFFECTED AREA	New	400.00	400.00
3	TO CHECK WIRING & FOCUS HEADLAMP	New	100.00	30.00
4	TUFF KOTE	New	150.00	30.00
Gross Labour Cost (\$)			1,450.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >