



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2134Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	CRACKED	430.90	430.90
1	FRT BUMPER CTR UPR MOULDING	CUT	368.50	368.50
1	FRT BUMPER SIDE SUPT LH	NOT NECESSARY	35.00	-
1	FRT BUMPER SIDE BRKT LH	NOT NECESSARY	28.00	-
1	HEADLAMP LH	NOT NECESSARY	1,993.65	-
1	RADIATOR GRILLE	CUT	1,409.10	1,409.10
	LESS 20% DISCOUNT		-853.03	-441.70
			3,412.12	1,766.80
	<u>NETT ITEMS</u>			
1	FRT NO PLATE W/TRIM CVR (N)	CRACKED	55.00	55.00
	LESS 10% DISCOUNT		-5.50	-5.50
			49.50	49.50
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAYPAINT CHARGE.		300.00	250.00
	CHECK ALL LIGHTING.		40.00	30.00
			740.00	630.00
GRAND TOTAL			4,201.62	2,446.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,950.00

Report Ref No. NS/INC21004562/T1tcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.