

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21004564/T1GS3Q2**Date:** 26/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210003047
Claimant Vehicle No :	SHC2954Z	Insured Vehicle No :	SGB40R
Date of Loss:	08/04/2021	Nature of Claim:	TP
		Claim No:	1508655847SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2954Z	Engine No:	G4LEKU211728
Make & Model:	HYUNDAI AE IONIQ, 1.6 (A)	Chassis No:	KMHC851CVKU146356
Reg. Date:	14/05/2019 (Man. Year: 2019)	Odometer:	251398 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,551.96	3,935.08	616.88	13.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,610.00	1,085.00	525.00	32.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,161.96	5,020.08	1,141.88	18.53
+ GST 7.00/7.00% (S\$)	431.34	351.41	79.93	18.53
Nett Amount (S\$)	6,593.30	5,371.49	1,221.81	18.53
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$125.19/day) (S\$)		375.57		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,899.06		
Global Sum Settlement (S\$)		5,800.00		

INSPECTION

Date of Assignment:	08/04/2021	
Date Inspected:	08/04/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER COVER	Deformed	430.90 FL	*430.90 FL
2	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*FRT BUMPER SIDE BRACKET LH	Deformed	28.00 FL	*28.00 FL
4	1		*FRT BUMPER BRACKET TOP LH	Not Necessary	35.00 FL	*- FL
5	1		*FRT BUMPER CENTRE MOULDING UPPER	Cut	368.50 FL	*368.50 FL
6	1		*FRT BUMPER MOULDING LH	Not Necessary	93.60 FL	*- FL
7	1		*FRT FENDER LH	Bent	588.80 FL	*588.80 FL
8	1		*FRT FENDER EMBLEM -BLUE DRIVE LH	Necessary	26.60 FL	*26.60 FL
9	1		*FRT WHEEL HUB CAP LH	Cut	346.40 FL	*346.40 FL
10	1		*DAY LIGHT LH	Not Necessary	642.50 FL	*- FL
11	1		*HEADLAMP LH	Cut	1,993.65 FL	*1,993.65 FL
12	1		*FRT FENDER SHIELD LH	Deformed	164.70 FL	*164.70 FL
13	1		*CARRIER ASSY FRONT END	Cracked	949.30 FL	*949.30 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,689.95	4,918.85
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,137.99	983.77
Total Parts (\$\$)	4,551.96	3,935.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	525.00
2	SPRAY PAINTING CHARGE	New	700.00	500.00
3	TUFF KOTE	New	50.00	30.00
4	CHECK WIRING	New	60.00	30.00
Gross Labour Cost (\$\$)			1,610.00	1,085.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >