

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21004566/AVCE2

**Date:** 08/09/2021

### REFERENCE

Insured/Claimant:	LI HONGTAO	Policy No:	1900165539		
Date of Loss:	03/04/2021	Nature of Claim:	OD	Claim No:	9525694703SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU3039D		
Make & Model:	AUDI Q7, 2.0 TFSI QU (A)	Engine No:	CYR091525
Reg. Date:	23/09/2019 (Man. Year: 2019)	Chassis No:	WAUZZZ4M9KD032971
Colour:	Black	Odometer:	31196 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$250,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	255/55 R19	Rear Tyre Size:	255/55 R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,464.00	6,132.96	13,331.04	68.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,092.00	3,632.00	5,460.00	60.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>28,556.00</b>	<b>9,764.96</b>	<b>18,791.04</b>	<b>65.80</b>
<b>- Excess (S\$)</b>	<b>1,000.00</b>	<b>1,000.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>27,556.00</b>	<b>8,764.96</b>	<b>18,791.04</b>	<b>68.19</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,928.92</b>	<b>613.55</b>	<b>1,315.37</b>	<b>68.19</b>
<b>Nett Amount (S\$)</b>	<b>29,484.92</b>	<b>9,378.51</b>	<b>20,106.41</b>	<b>68.19</b>

### INSPECTION

Date of Assignment:	12/04/2021		
Date Inspected:	08/04/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER - UPPER	Deformed	1,362.00 FS	*1,089.60 FS
2	1		*REAR BUMPER - MIDDLE	Deformed	2,070.00 FS	*1,656.00 FS
3	2		*REAR BUMPER FIXING PARTS	Not Necessary	208.00 FS	*- FS
4	1		*REAR BUMPER LOWER SPOILER	Deformed	1,261.00 FS	*1,008.80 FS
5	1		*REAR BUMPER LOWER SPOILER TRIM	Not Necessary	107.00 FS	*- FS
6	1		*REAR BUMPER CARRIER	Not Necessary	1,417.00 FS	*- FS
7	1		*REAR BUMPER HOLDING STRAP	Not Necessary	182.00 FS	*- FS
8	1		*REAR BUMPER GUIDE SECTION - CENTER	Not Necessary	142.00 FS	*- FS
9	2		*REAR BUMPER SEAL - LH / RH	Not Necessary	28.00 FS	*- FS
10	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	126.00 FS	*- FS
11	2		*REAR PARKING AID SENSOR	Not Necessary	488.00 FS	*- FS
12	1		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
13	1		*REAR BOOT LID	Repair	6,018.00 FS	*- FS
14	1		*REAR BOOT LID ATTACHMENT PARTS	Not Necessary	344.00 FS	*- FS
15	1		*REAR BOOT LID LOCK	Not Necessary	248.00 FS	*- FS
16	1		*REAR BOOT COVER CAP	Not Necessary	13.00 FS	*- FS
17	1		*REAR BOOT GASKET	Not Necessary	292.00 FS	*- FS
18	1		*REAR BOOT PACKING ADHESIVE	Not Necessary	19.00 FS	*- FS
19	1		*AUDI EMBLEM	Necessary	138.00 FS	*110.00 FS
20	1		*Q7 EMBLEM	Necessary	99.00 FS	*79.04 FS
21	1		*QUATTRO EMBLEM	Necessary	99.00 FS	*79.04 FS
22	1		*REAR WINDOW	Not Necessary	1,174.00 FS	*- FS
23	1		*PRIMER	Not Necessary	20.00 FS	*- FS
24	2		*REAR WINDOW SIDE SPOILER - LH / RH	Not Necessary	462.00 FS	*- FS
25	1		*REAR LID SPOILER FIXING PARTS	Not Necessary	62.00 FS	*- FS
26	1		*REAR BUMPER TAILLIGHT - RH	Cracked	359.00 FS	*286.80 FS
27	2		*REAR WHEEL ARCH COVER - LH / RH	Necessary	754.00 FS	*602.40 FS
28	1		*FRONT WING MIRROR MOUNTING - RH	Cut	1,508.00 FS	*1,206.40 FS
29	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
30	1		*SUNDRIES	Necessary	250.00 FS	*14.88 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **19,464.00**      **6,132.96**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM. WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY	New	480.00	0.00
3	TO RENEW REAR WINDSCREEN TO FACILITATE REAR LID RENEWAL	New	480.00	0.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	400.00	0.00
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	0.00
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,700.00	600.00
7	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER, REAR LID AND BOTH REAR WHEEL ARCH TRIMS	New	4,000.00	2,200.00
8	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY	New	280.00	280.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$)</b>			<b>9,092.00</b>	<b>3,632.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >