



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
KONG TIAN LOCK 21 JALAN LABU AYER SINGAPORE 538033 Contact No Mobile: 98190318	Cust No/Name /KONG TIAN LOCK Reg No/Reg Date SMM8720E*KC17/ 18/07/201 Date In/Mileage / 0 Chassis No KNAF3416MK5044585 Engine No G4FGKH737233 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	09/04/2021/ 16:39		442 / CocoLu	31771			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								800 1600.00
RENEW FRT BUMPER, FRT FENDER LH, FRT SUPPORT PANEL, 2 x 400								+600
REPAIR FRT FENDER RH,								
E PNT98000								700 1050.00
SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH, FRT FENDER RH 2 x 350								
E PNT88000								100.00
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR								
M SUNDRY								80.00
TOP UP AIRCON GAS								
M SUNDRY								50.00
FRT NUMBER PLATE WITH FRAME								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								20.00
Sundry								
A 90000001								400.00
RENEW FRT UNDER CARRIAGE								
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								60.00
TRANSFER FRT RIGHT & LEFT RIM								
M SUNDRY								360.00
FRT LEFT RIM								
M SUNDRY								360.00
FRT RIGHT RIM								
M SUNDRY								300.00
SUPPLY FRT LEFT TYRE								
M SUNDRY								300.00
SUPPLY FRT RIGHT TYRE								
M COVER-FR BUMPER					1.00	633.00	00.00	633.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
KONG TIAN LOCK	Cust No/Name /KONG TIAN LOCK
21 JALAN LABU AYER	Reg No/Reg Date SMM8720E*KC17/ 18/07/201
SINGAPORE 538033	Date In/Mileage / 0
Contact No Mobile: 98190318	Chassis No KNAF3416MK5044585
	Engine No G4FGKH737233
	Make/Model KIA/CERATO 1.6 A EX G333
	Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	09/04/2021/ 16:39		442 / CocoLu	31771		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	GRILLE-FRONT BUMPER	CUT		1.00	262.00	00.00	262.00
M	COVER-FR BUMPER FOG LAMP, LH	CUT x nn		1.00	15.00	00.00	15.00
M	LAMP ASSY-FRONT FOG, LH	X N/A		1.00	303.00	00.00	303.00
M	GRILLE ASSY-RADIATOR	X N/A		1.00	328.00	00.00	328.00
M	MOULDING-FRONT BUMPER, LH	CUT		1.00	36.00	00.00	36.00
M	LAMP ASSY-SIDE REPEATER, LH	CUT		1.00	143.00	00.00	143.00
M	AIR DUCT-FR BUMPER, LH	BR		1.00	14.00	00.00	14.00
M	ABSORBER-FRONT BUMPER ENERGY	X N/A		1.00	84.00	00.00	84.00
M	BRACKET-FR BUMPER UPR SIDE MTG	X N/A		1.00	22.00	00.00	22.00
M	GUARD ASSY-FRONT WHEEL, RH	X N/A		1.00	95.00	00.00	95.00
M	GUARD ASSY-FRONT WHEEL, LH	BR		1.00	95.00	00.00	95.00
M	ORNAMENT-KIA NO.115	APC		1.00	32.00	00.00	32.00
M	PANEL-FENDER, LH	X N/A		1.00	430.00	00.00	430.00
M	BEAM COMPLETE-FR BUMPER	X N/A		1.00	497.00	00.00	497.00
M	CARRIER ASSY-FRONT END MODULE	BR		1.00	675.00	00.00	675.00
M	CROSSMEMBER COMPL	BT		1.00	1156.00	00.00	1156.00
M	ARM COMPLETE-FR LWR, RH	X N/A		1.00	286.00	00.00	286.00
M	ARM COMPLETE-FR LWR, LH	X N/A		1.00	286.00	00.00	286.00
M	LAMP ASSY-HEAD, LH	BR		1.00	1219.00	00.00	1219.00
M	BLOWER ASSY	BR		1.00	656.00	00.00	656.00
M	RADIATOR ASSY	BT		1.00	646.00	00.00	646.00
M	PANEL ASSY-UNDER COVER	BR		1.00	117.00	00.00	117.00
P	HUB ASSY-FR WHEEL	X N/A		2.00	436.00	00.00	872.00
M	GEAR ASSY-STEERING	BT		1.00	770.00	00.00	770.00

9/4/21, 4:30pm
Steve CLKK)
OO-NM AL
EXCIS-?
P/P
My Bel sky
7 dgs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Confirm & accepted by

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Authorized signatory and company stamp

Nett	14,622.00
7% GST on	1023.54
Total Payable	15,645.54

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.