

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21004568/T1TF3E2

**Date:** 21/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SMA1922Z

**Insured Vehicle No :** GBL843Y

Date of Loss: 03/04/2021

Nature of Claim: TP Claim No: 4843613936SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA1922Z**

Make & Model: HONDA GRACE, 1.5 (A)

Engine No: L15B4170563

Reg. Date: 30/05/2018 (Man. Year: 2017)

Chassis No: GM61100546

Colour: Blue

Odometer: 36045 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 12/04/2021

Date Inspected: 12/04/2021 Inspected At:

Alpha Car Services Pte Ltd (HQ)  
Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay  
Singapore 417883

Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Missing	0.00 F	*- F
2	1		*FRT BUMPER	Deformed	0.00 F	*- F
3	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
4	2		*FRT BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
5	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
6	1		*FRT BUMPER TOW COVER	Cut	0.00 F	*- F
7	1		*FRT BUMPER GRILLE	Deformed	0.00 F	*- F
8	1		*FRT GRILLE	Cracked	0.00 F	*- F
9	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
10	1		*FRT GRILLE CHROME MOULDING	Cut	0.00 F	*- F
11	1		*FRT SUPPORT PANEL	Repair	0.00 F	*- F
12	1		*FRT SUPPORT PANEL TOP GARNISH COVER	* Check	0.00 F	*- F
13	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
14	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
15	1		*BONNET	Bent	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >