



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 8995R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	450.80	-
10	FRONT BUMPER CLIP (CONSISTENT)	NOT NECESSARY	40.00	-
1	FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	SERVICEABLE	107.20	-
1	FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	SERVICEABLE	107.20	-
1	FRONT BUMPER UPPER GRILLE (CONSISTENT)	SERVICEABLE	321.90	-
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	SERVICEABLE	148.60	-
1	FRONT BUMPER TOW COVER LH (CONSISTENT)	SERVICEABLE	25.70	-
1	RH WING MIRROR (COVER) (CONSISTENT)	TO REPAIR SEE LABOUR	87.40	-
	LESS 25% DISCOUNT		-322.20	-
			966.60	-
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER ,RH SIDE MIRROR).INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND RH WING MIRROR (COVER) .		400.00	150.00
	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA .(FRONT BUMPER ,RH SIDE MIRROR).		400.00	260.00
	TO CHECK WIRING .	NOT NECESSARY	50.00	-
			850.00	410.00
GRAND TOTAL			1,816.60	410.00
RECOMMENDED COST OF REPAIRS				410.00

Report Ref No. CC4/ASM18011089/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.