

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG21001911/GVF3E2-1
Date: 21/05/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29067068QMX
Claimant Vehicle No : SMV8168C Insured Vehicle No : SJN3694K
Date of Loss: 29/01/2021 Nature of Claim: TP Claim No: 633457

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMV8168C**
Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 2ZR0A09646
Reg. Date: 29/09/2017 (Man. Year: 2017) Chassis No: JTDGG20W80J007847
Colour: White Odometer: 20558 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,363.20	2,841.77	2,521.43	47.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,146.00	1,900.00	246.00	11.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,509.20	4,741.77	2,767.43	36.85
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	7,509.20	3,800.00	3,709.20	49.40
+ GST 7.00/7.00% (S\$)	525.64	266.00	259.64	49.40
Nett Amount (S\$)	8,034.84	4,066.00	3,968.84	49.40

INSPECTION

Date of Assignment: 09/02/2021
Date Inspected: 22/02/2021 Inspected At: Mirage Motorwerkz Pte Ltd (HQ)
10 KAKI BUKIT ROAD 2 #01-29 FIRST EAST CENTRE
Singapore 417868
Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 May 2021)
Parts: M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV8168C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent / Kinked	1,574.80 FL	*1,290.00 FL
2	1		*TAIL GATE INNER LOCK	Bent / Jammed	345.80 FL	*345.80 FL
3	1		*TAIL GATE PLATE VALVE METRIC	Necessary	91.20 FL	*91.20 FL
4	1		*TAIL GATE WEATHERSTRIP	Ripped / Necessary	205.40 FL	*205.40 FL
5	2		*TAIL GATE REFLECTOR	Serviceable	597.00 FL	*- FL
6	1		*TAIL GATE INNER BOARD	Serviceable	654.10 FL	*- FL
7	1		*ANTENNA ELECTRICAL	Damaged	115.00 FL	*115.00 FL
8	1		*REAR BUMPER	Deformed	889.00 FL	*579.00 FL
9	2		*REAR BUMPER REFLECTOR	Serviceable	170.00 FL	*- FL
10	2		*TAIL LAMP	Serviceable	1,116.90 FL	*- FL
11	1		*REAR END PANEL	Bent	624.10 FL	*495.00 FL
12	1		*REAR END PANEL TOP GARNISH	Deformed	214.30 FL	*214.30 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	55.00 FS	*30.00 FS
14	1		*REVERSE SENSOR	Malfunction	250.00 FS	*200.00 FS
15	1		*REAR END PANEL SEALANT	Necessary	40.00 FS	*40.00 FS
16	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
17	1		*TAIL GATE WINDSCREEN GLASS SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,012.60	3,675.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,649.40	833.93
Total Parts (\$\$)	5,363.20	2,841.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL	New	800.00	800.00
2	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	50.00	50.00
3	CONDUCT WATER LEAK TEST FOR REAR PORTION ASSOCIATED REPAIR WORKS	New	48.00	0.00
4	TRANSFER OF EXISTING TAILGATE MECHANISM TO NEW TAILGATE	New	96.00	60.00
5	REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING	New	81.60	40.00
6	REMOVE AND REFIX TAILGATE REAR WINDSCREEN GLASS. (2-MAN JOB)	New	168.00	120.00
7	WIRING AND BULB CHECKING	New	38.40	30.00
8	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	864.00	800.00
			Gross Labour Cost (\$)	2,146.00
				1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >