



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 9824J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BONNET	TO REPAIR SEE LABOUR	1,502.00	-
1	FRONT O/S HEADLAMP	DAMAGED	2,729.00	2,729.00
1	FRONT BUMPER	DAMAGED	888.00	888.00
1	FRONT BUMPER O/S DAY LAMP	INTACT	265.00	-
1	FRONT O/S FENDER	DAMAGED	787.00	787.00
1	FRONT O/S FENDER INNER GARNISH	DAMAGED	80.00	80.00
1	FRONT O/S FENDER "LINE" EMBLEM	DAMAGED	39.00	39.00
1	FRONT O/S FENDER INNER SHIELD	DAMAGED	224.00	224.00
1	FRONT O/S FENDER INNER SPONGE	DAMAGED	68.00	68.00
1	FRONT O/S WHEEL HUB WITH BEARING	DAMAGED	452.00	452.00
1	FRONT O/S SHOCK ABSORBER	NOT NECESSARY	508.00	-
1	FRONT O/S KNUCKLE ARM	NOT NECESSARY	899.00	-
1	FRONT O/S LOWER ARM	NOT NECESSARY	544.00	-
1	FRONT O/S TIE ROD	NOT NECESSARY	76.00	-
	LESS 20% DISCOUNT		-1,812.20	-1,053.40
			7,248.80	4,213.60
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT O/S FENDER INNER SHIELD CLIP (SN)	NECESSARY	50.00	20.00
1	FRONT O/S FENDER SOUND PROOF INSULAROR (SN)	NECESSARY	450.00	250.00
1	FRONT O/S TYRE (SN)	NOT NECESSARY	450.00	-
1	FRONT O/S WHEEL RIM (SN)	DAMAGED	750.00	600.00
			1,700.00	870.00
<b><u>LABOUR</u></b>				
	TO CHECK WIRING, LIGHTING AND RESETTNG HEADLAMPS FOCUSING.		80.00	30.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.		400.00	150.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	80.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		100.00	30.00

Report Ref No. CS3/AIG20013574/T1tf3e2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OR FRONT BONNET.		1,080.00	500.00
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	500.00
			2,810.00	1,290.00
GRAND TOTAL			11,758.80	6,373.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,100.00

Report Ref No. CS3/AIG20013574/T1tf3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.