

PHOTOCOPY

C L APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Foo Kim Long Allen
C/o: Sheng Li Lai
2 Kaki Bukit Avenue 2
#01-36 Kaki Bukit Autohub, Singapore 417

Invoice No. : CL/200617

Ref No. : SLL/12/2001/TP

Date : 22 December 2020

DESCRIPTION	AMOUNT
OUR SERVICE FEE CHARGES:	
- SURVEY INSPECTION FOR VEHICLE NO. <u>SMH 9824 J</u> - RESURVEY INSPECTION - DIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS) - TRANSPORTATION	
GRAND TOTAL	S\$ 642.00

E & O. E

All cheque payment should be "Crossed" and made payable to " C L APPRAISER PTE LTD "

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd



24 Peshurst Place, Singapore 556440

Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783

Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Foo Kim Long Allen
C/o: Sheng Li Lai
2 Kaki Bukit Avenue 2
#01-36 Kaki Bukit Autohub, Singapore 417921

Date : 22 December 2020
Our ref : SLL/12/2001/TP

Accident Date : 06 December 2020
Inspection Date : 10 December 2020
Repairer Name : Sheng Li Lai
2 Kaki Bukit Avenue 2
#01-36 Kaki Bukit Autohub, Singapore 417921

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No	: SMH 9824 J	Year / Capacity	: 2019 / 1353 cc
Make / Model	: Hyundai I30	Colour	: Grey
Chassis No	: TMAH3813VKJ045660	Mileage	: 15798
Engine No	: G4LDJD207797		

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Michelin	225/45 R17	5 mm	Sport
Front Offside	: Michelin	225/45 R17	5 mm	Sport
Rear Nearside	: Michelin	225/45 R17	5 mm	Sport
Rear Offside	: Michelin	225/45 R17	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the o/s front portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 72 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 7,400.00** on a contractual basis.

Under normal circumstances, the repair period would be about 6 (Six) working days.

Vehicle Registration No.: SMH 9824 J

Our Ref No.:

SLL/12/2001/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front bonnet	Repair	\$ 1,502.00	
1	Front o/s headlamp	Damage	\$ 2,729.00	\$ 2,729.00
1	Front bumper	Damage	\$ 888.00	\$ 888.00
1	Front bumper o/s day lamp	Intact	\$ 265.00	
1	Front o/s fender	Damage	\$ 787.00	\$ 787.00
1	Front o/s fender inner garnish	Damage	\$ 80.00	\$ 80.00
1	Front o/s fender "Line" emblem	Damage	\$ 39.00	\$ 39.00
1	Front o/s fender inner shield	Damage	\$ 224.00	\$ 224.00
1	Front o/s fender inner sponge	Damage	\$ 68.00	\$ 68.00
1	Front o/s wheel hub with bearing	Damage	\$ 452.00	\$ 452.00
1	Front o/s shock absorber	Damage	\$ 508.00	\$ 508.00
1	Front o/s knuckle arm	Damage	\$ 899.00	\$ 899.00
1	Front o/s lower arm	Damage	\$ 544.00	\$ 544.00
1	Front o/s tie rod	Damage	\$ 76.00	\$ 76.00
			\$ 9,061.00	\$ 7,294.00
			<i>Less 20%</i>	<i>\$ 1,812.20</i>
Total Cost - List Items			\$ 7,248.80	\$ 5,835.20

SPECIAL NETT ITEMS

1	Front o/s fender inner shield clip (1 set)	Necessary	\$ 50.00	\$ 50.00
1	Front o/s fender sound proof insulator	Necessary	\$ 450.00	\$ 450.00
1	Front o/s tyre (Depreciation)	Damage	\$ 450.00	\$ 225.00
1	Front o/s wheel rim	Damage	\$ 750.00	\$ 750.00
Total Cost - Special Nett items			\$ 1,700.00	\$ 1,475.00

Total cost of parts

\$ 8,948.80	\$ 7,310.20
--------------------	--------------------

Vehicle Registration No.: SMH 9824 J

Our Ref No.: SLL/12/2001/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 8,948.80	\$ 7,310.20

LABOUR

1	To check wiring , lighting and resetting headlamps focusing.	\$ 80.00	\$ 50.00
2	To remove and refit front undercarriage.	\$ 400.00	\$ 300.00
3	To conduct wheel alignment.	\$ 150.00	\$ 120.00
4	To apply undercoating on repaired and replaced panel.	\$ 100.00	\$ 60.00
5	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,080.00	\$ 750.00
6	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,000.00	\$ 660.00

GRAND TOTAL

\$ 11,758.80	\$ 9,250.20
---------------------	--------------------

Vehicle Registration No.: SMH 9824 J

Our Ref No.: SLL/12/2001/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 7,400.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser