

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21004582/BTF3E2

Date: 01/06/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00006382100
Claimant Vehicle No: SLJ893U Insured Vehicle No: GBJ2099B
Date of Loss: 05/04/2021 Nature of Claim: TP Claim No: SNM21D201965/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLJ893U
Make & Model: HONDA CITY, 1.5 CVT (A) Engine No: L15Z14112365
Reg. Date: 28/11/2016 (Man. Year: 2016) Chassis No: MRHGM6660HP000226
Colour: Silver Odometer: 41404 km
Engine Capacity: 1497 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R16 Rear Tyre Size: 185/55 R16
Front Left Side: APLUS 6 mm Rear Left Side: APLUS 6 mm
Front Right Side: APLUS 6 mm Rear Right Side: APLUS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,900.24	2,105.20	795.04	27.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,290.00	1,060.00	45.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,250.24	3,395.20	1,855.04	35.33
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	5,250.24	2,700.00	2,550.24	48.57
+ GST 7.00/7.00% (S\$)	367.52	189.00	178.52	48.57
Nett Amount (S\$)	5,617.76	2,889.00	2,728.76	48.57

INSPECTION

Date of Assignment: 09/04/2021
Date Inspected: 14/04/2021 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875
Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jun 2021)
Parts:	143	HONDA CITY 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ893U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	580.20 FL	*580.20 FL
2	1		*BOOTLID CENTRE EMBLEM	Necessary	27.30 FL	*27.30 FL
3	1		*BOOTLID CITY EMBLEM	Necessary	26.20 FL	*26.20 FL
4	1		*BOOTLID I-VTEC EMBLEM	Necessary	22.40 FL	*22.40 FL
5	1		*BOOTLID LOCK	Jammed	71.30 FL	*71.30 FL
6	1		*BOOTLID LOCK CATCH	Not Damaged	28.40 FL	*- FL
7	1		*BOOTLID RH HINGE	Not Damaged	63.80 FL	*- FL
8	1		*BOOTLID LH HINGE	Not Damaged	63.80 FL	*- FL
9	1		*BOOTLID CHROME MOULDING	Not Damaged	74.60 FL	*- FL
10	1		*BOOTLID RH LAMP ASSY	Cut	90.30 FL	*90.30 FL
11	1		*BOOTLID LH LAMP ASSY	Not Damaged	90.30 FL	*- FL
12	1		*BOOTLID WEATHERSTRIP	Distorted	73.70 FL	*73.70 FL
13	1		*REAR BUMPER	Broken	486.70 FL	*486.70 FL
14	1		*REAR BUMPER RH SIDE RETAINER	Necessary	20.80 FL	*20.80 FL
15	1		*REAR BUMPER RH SIDE REFLECTOR	Broken	28.60 FL	*28.60 FL
16	1		*REAR BUMPER LH SIDE REFLECTOR	Not Damaged	28.60 FL	*- FL
17	1		*RH TAILLAMP ASSY	Cut	280.70 FL	*280.70 FL
18	1		*SET RH TAILLAMP CLIPS LOCK	Not Necessary	13.00 FL	*- FL
19	1		*LH TAILLAMP ASSY	Not Damaged	280.70 FL	*- FL
20	1		*SET LH TAILLAMP CLIPS LOCK	Not Damaged	13.00 FL	*- FL
21	1		*END PANEL	Bent	444.30 FL	*405.50 FL
22	1		*END PANEL INNER GARNISH	Broken	66.60 FL	*66.60 FL
23	1		*REAR BUZZER	Not Damaged	61.30 FL	*- FL
24	1		*SPARE TYRE TOP BOARD	Broken	80.40 FL	*80.40 FL
25	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
26	1		*REAR BUMPER REVERSE SENSOR (SET OF 4)	Short Circuit	400.00 FS	*250.00 FS
27	1		*REAR BUMPER LH SIDE RETAINER	Necessary	20.80 FL	*20.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,507.80	2,561.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	607.56	456.30
Total Parts (\$\$)	2,900.24	2,105.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND RE-ALIGN ALL AFFECTED PANELS	New	900.00	600.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	70.00	30.00
4	APPLY RUST COATING ON AFFECTED AREAS	New	80.00	0.00
5	REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR	New	100.00	60.00
6	REMOVE AND REINSTALL REAR INNER TRIMS AND GARNISH TO FACILITATE REPAIRS	New	200.00	0.00
Gross Labour Cost (\$\$)			2,350.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >