7/16/2021 Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/GRB21004583/KBS3Q2

Date:

16/07/2021

REFERENCE

Date of Loss:

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D21MFL0000447

Claimant Vehicle No :

SMJ3775X 09/04/2021

Insured Vehicle No:

Nature of Claim:

SLR2567G TP

Claim No: MFL2021D0001672

LEB5614212

GB71078343

125443 km

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMJ3775X

Make & Model: HONDA FREED, 1.5 (A)

Reg. Date: 01/03/2019 (Man. Year: 2018)

Colour: Metallic Grey

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Se

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pr

Pre-accident Condition:

Engine No:

Chassis No:

Odometer:

**CONDITION OF TYRES** 

Front Tyre Size: 185/65 R15

Rear Tyre Size: Rear Left Side: 185/65 R15 West Lake 8 mm

Front Left Side: Front Right Side: West Lake 8 mm
West Lake 8 mm

Rear Right Side:

West Lake 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,549.70	2,575.36	1,974.34	43.39
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,480.00	2,040.00	440.00	17.74
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	7,029.70	4,615.36	2,414.34	34.34
	Approved Total (Overridden) (S\$)		3,650.00		

Nett Amount (S\$)	7,029.70	3,650.00	3,379.70	48.08
+ Loss of Use (7.	0 x S\$80.00/day) (S\$)	560.00		
	Nett Liability (S\$)	4,210.00		

**INSPECTION** 

Date of Assignment: 12/04/2021

Lkw Auto Services (HQ) 23 HUME AVENUE #05-02 HUME PARK 2 Date Inspected: Inspected At: 12/04/2021

Singapore 598729

Estimated Period of Repair: 7.0 days

KENNETH KONG Adjuster: Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jun 2021)

HONDA FREED 1.5 (A) (Catalogue:Merimen Singapore 1.0) Parts: M1-MPV

(Price-denominated Standard List) Labour: Repairer's

(Unsubmitted, no print-code for SMJ3775X) **Print Code:** 

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*SET FRONT DOOR FRAME STICKER	Necessary	78.30 F	*48.00 FL
2	1	*REAR DOOR	Bent	1,025.80 F	*985.40 FL
3	1	*REAR DOOR REGULATOR GEAR	Serviceable	317.90 F	*- FL
4	1	*REAR DOOR LOCK	Repair	230.80 F	*- FL
5	1	*SET REAR DOOR FRAME STICKER	Necessary	68.50 F	*48.00 FL
6	1	*REAR DOOR ROLLER BRACKET	Serviceable	291.00 F	*-FL
7	1	*REAR FENDER	Bent	936.80 F	*912.40 FL
8	1	*REAR BUMPER	Mtg Cracked	895.30 F	*895.30 FL
9	1	*REAR BUMPER SIDE RETAINER	Serviceable	81.00 F	*- FL
10	1	*REAR SHOCK ABSORBER	Serviceable	237.50 F	*-FL
11	1	*WHEEL HUB BEARING	Bent	326.80 F	*280.10 FL
12	1	*TUBE SIDE GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
F=Fr	anchise part. S=SpcNett. I	_=ListItemDisc.			
			Sub Total (S\$)	4,549.70	3,209.20
			- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	633.84
			Total Parts (S\$)	4,549.70	2,575.36

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	<u>our Items</u>			
1	TO TRANSFER FRONT /ROOR DOOR ACCESSORIES	New	180.00	120.00
2	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE ,PANEL BEAT AND REALIGN THE NECESSARY AFFECTE AREAS	D New	800.00	700.00
3	TO CHECK WIRING SYSTEM	New	30.00	20.00
4	TO REMOVE REAR SIDE GLASSES TO ENABLE REPAIR	New	90.00	50.00
5	TO REMOVE CARPET ,TRIMMING AND SEATS TO ENABLE REPAIR	New	150.00	100.00
6	TO INSTALL REVERSE SENSORS	New	60.00	50.00
7	TO APPLY PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	850.00	800.00
8	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS	New	60.00	30.00
9	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	60.00	60.00
10	TO REMOVE AND INSTALL REAR UNDERCARRIAGE PARTS TO ENABLE REPAIR	New	120.00	50.00
11	TO PERFORM 4 WHEELS COMPUTERISED ALIGNMENT	New	80.00	60.00
	Gross	Labour Cost (S\$)	2,480.00	2,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >