

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21004592/T1TF3E2**Date:** 10/05/2021REFERENCE

| | | | | |
|------------------------------|--------------------------------------|-----------------------------|----------|--------------------|
| Handling Insurer: | Tokio Marine Insurance Singapore Ltd | Policy No: | MM000072 | |
| Claimant Vehicle No : | SHD6622A | Insured Vehicle No : | SLR1903B | |
| Date of Loss: | 09/04/2021 | Nature of Claim: | TP | Claim No: M2101738 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--|-------------|-------------------|
| Reg No: | SHD6622A | | |
| Make & Model: | MERCEDES-BENZ E220, 2.1 D CDI BlueEFFICIENCY (A) | Engine No: | 65192433223140 |
| Reg. Date: | 23/03/2016 (Man. Year: 2015) | Chassis No: | WDD2120012B309192 |
| Colour: | White | Odometer: | 606747 km |
| Engine Capacity: | 2143 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|------|-------------------------|-----|--------------------------|------|
| General Condition: | Good | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | Good |

CONDITION OF TYRES

| | | | |
|-------------------|------------|------------------|------------|
| Front Tyre Size: | 225/55 R16 | Rear Tyre Size: | 225/55 R16 |
| Front Left Side: | Giti 6 mm | Rear Left Side: | Giti 6 mm |
| Front Right Side: | Giti 6 mm | Rear Right Side: | Giti 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 3,702.00 | 3,042.00 | 660.00 | 17.83 |
| Miscellaneous Items | 11.00 | 11.00 | 0.00 | 0.00 |
| Labour | 1,720.00 | 1,130.00 | 590.00 | 34.30 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 5,433.00 | 4,183.00 | 1,250.00 | 23.01 |
| Approved Total (Overridden) (S\$) | | 3,350.00 | | |
| (S\$) | 5,433.00 | 3,350.00 | 2,083.00 | 38.34 |
| + GST 7.00/7.00% (S\$) | 380.31 | 234.50 | 145.81 | 38.34 |
| Nett Amount (S\$) | 5,813.31 | 3,584.50 | 2,228.81 | 38.34 |

INSPECTION

| | | | |
|-----------------------------|------------|-------------------|---|
| Date of Assignment: | 12/04/2021 | Present Location: | ComfortDelGro Engineering Pte Ltd (Loyang) |
| Date Inspected: | 12/04/2021 | Inspected At: | ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969 |
| Estimated Period of Repair: | 3.0 days | | |

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 May 2021)

Parts: 143 MERCEDES-BENZ E220 2.1 D CDI BlueEFFICIENCY (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD6622A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Reference | Amount |
|-------------------------|-----|----------|----------------------------------|-------------|-------------|-----------|--------------|
| 1 | 1 | | *REAR BUMPER | Deformed | 1,510.00 FL | - | *1,510.00 FL |
| 2 | 1 | | *REAR BUMPER UNDER COVER | Deformed | 1,150.00 FL | - | *325.00 FL |
| 3 | 2 | | *REAR BUMPER UNDER BRACKET RH/LH | Cracked | 270.00 FL | - | *270.00 FL |
| 4 | 1 | | *REAR BUMPER MAT | Necessary | 50.00 F | - | *50.00 F |
| 5 | 1 | | *REAR BUMPER REVERSE SENSOR | Not Working | 388.00 F | - | *388.00 F |
| Supplementary #1 | | | | | | | |
| 6 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 1,150.00 FL | - | *1,150.00 FL |

F=Franchise part. L=ListItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (S\$) | 4,518.00 | 3,693.00 |
| - List Item Discount on L Items 20.00/20.00% (S\$) | 816.00 | 651.00 |
| Total Parts (S\$) | 3,702.00 | 3,042.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

| No | Qty | Particulars | Repairer's | Amount |
|----------------------------|-----|----------------------|------------|--------|
| <u>Miscellaneous Items</u> | | | | |
| 1 | 1 | OD/TP Case (Insurer) | 11.00 | 11.00 |
| Sub Total (\$\$) | | | 11.00 | 11.00 |

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|--------------------------------------|----------|------------|----------|
| <u>Labour Items</u> | | | | |
| 1 | PANEL BEATING - BOOTLID GARNISH ETC | New | 800.00 | 600.00 |
| 2 | SPRAY PAINTING - BOOTLID GARNISH ETC | New | 800.00 | 500.00 |
| 3 | R/I REVERSE SENSOR | New | 120.00 | 30.00 |
| Gross Labour Cost (\$\$) | | | 1,720.00 | 1,130.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >