

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21004593/T1QF3E2

**Date:** 21/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070104141  
**Claimant Vehicle No :** GBJ6905Z **Insured Vehicle No :** SJX1881Y  
Date of Loss: 08/04/2021 Nature of Claim: TP Claim No: 3702155433SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ6905Z**  
Make & Model: SUZUKI EVERY, 658cc GA (A) Engine No: R06A2129839  
Reg. Date: 15/07/2019 (Man. Year: 2017) Chassis No: DA17V256224  
Colour: White Odometer: 40330 km  
Engine Capacity: 658 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 155/70 R13 Rear Tyre Size: 155/70 R13  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 12/04/2021  
Date Inspected: 12/04/2021 Inspected At: A-Tec Automotive Pte Ltd (HQ)  
8 Kaki Bukit Avenue 4 # 05-27 Premier  
Singapore 415875  
Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Cracked	0.00 F	*- F
2	1		*REAR BUMPER	Deformed	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR END PANEL	Bent	0.00 F	*- F
5	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
6	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
7	1		*TAILGATE	Bent	0.00 F	*- F
8	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
9	1		*TAILGATE OUTER HANDLE	Cut	0.00 F	*- F
10	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
11	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
12	1		*TAILGATE LOCK	Bent	0.00 F	*- F
13	1		*TAILGATE RUBBER	Deformed	0.00 F	*- F
14	1		*TAILGATE INNER BOARD	* Check	0.00 F	*- F
15	1		*SPARE TYRE BRACKET	* Check	0.00 F	*- F
16	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
17	1		*STICKER 70KM/H	Necessary	0.00 F	*- F
18	1		*STICKER EVERY	Necessary	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >