

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21004596/UPS3Q2
Date: 19/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MPC0001166
Claimant Vehicle No :	SMC186C	Insured Vehicle No :	SLL4572J
Date of Loss:	10/04/2021	Nature of Claim:	TP
		Claim No:	MPC2021D0001573

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC186C		
Make & Model:	MAZDA 3, 1.5 HATCHBACK DELUXE EU6 (A)	Engine No:	P520450560
Reg. Date:	31/10/2017 (Man. Year: 2017)	Chassis No:	JM6BN22A8H0157865
Colour:	Silver	Odometer:	133129 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,931.10	13,979.28	14,951.82	51.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,120.00	4,790.00	1,330.00	21.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,051.10	18,769.28	16,281.82	46.45
Approved Total (Overridden) (S\$)		14,400.00		

Nett Amount (S\$)	35,051.10	14,400.00	20,651.10	58.92
		+ Car Rental (14.0 x S\$100.00/day) (S\$)	1,400.00	
		+ Other Costs (S\$)	150.00	
		Nett Liability (S\$)	15,950.00	
		Global Sum Settlement (S\$)	15,850.00	

INSPECTION

Date of Assignment: 12/04/2021

Date Inspected: 12/04/2021

Estimated Period of Repair: 15.0 days

Inspected At: Zoom Autowerks Pte Ltd
832 SIMS AVENUE #12-884 EUNOSVILLE
Singapore 400832

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value: \$61,000.00(est) less LTA Rebate: \$37,894.00(est) = Nett Value :\$23,106.00(est)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 May 2021)
Parts:	144	MAZDA 3 1.5 HATCHBACK DELUXE EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC186C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,425.00 FL	*1,062.50 FL
2	2		*REAR BUMPER SIDE RETAINER	Bent	130.00 FL	*130.00 FL
3	2		*REAR BUMPER BRACKET	Not Necessary	156.00 FL	*- FL
4	1		*REAR BUMPER REFLECTOR	O/S Broken	256.00 FL	*54.90 FL
5	1		*REAR BUMPER CENTRE BRACKET	No such part	28.00 FL	*- FL
6	2		*REAR BUMPER CORNER BRACKET	No such part	50.00 FL	*- FL
7	1		*SET REAR BUMPER SENSOR BRACKET	No such part	68.00 FL	*- FL
8	4		*REAR BUMPER SENSOR	Shorted	648.00 FS	*200.00 FS
9	1		*REAR BUMPER SENSOR HARNESS	Not Necessary	240.00 FL	*- FL
10	2		*REAR BUMPER TOW GARNISH	Missing	30.00 FL	*30.00 FL
11	1		*REAR BUMPER REINFORCEMENT	Distorted	498.00 FL	*491.80 FL
12	1		*REAR BUMPER CLIPS	Necessary	60.00 FL	*50.00 FL
13	1		*REAR BOOTLID PANEL	Bent / Buckled	1,985.00 FL	*1,026.70 FL
14	1		*REAR BOOTLID INNER TRIM	Not Necessary	596.00 FL	*- FL
15	1		*REAR BOOTLID INNER LOCK	Bent	485.00 FL	*164.60 FL
16	1		*REAR BOOTLID CATCH	Not Necessary	68.00 FL	*- FL
17	1		*REAR BOOTLID LOGO	Necessary	75.00 FL	*65.80 FL
18	1		*REAR BOOTLID NAME PLATE	Not fitted	74.00 FL	*- FL
19	2		*REAR BOOTLID LAMP	Cracked	1,590.00 FL	*530.00 FL
20	1		*REAR BOOTLID WEATHERSTRIP	Twisted	375.00 FL	*130.60 FL
21	2		*REAR TAILLAMPS	Cracked	2,050.00 FL	*1,830.00 FL
22	1		*REAR END PANEL	Badly Dented	955.00 FL	*395.30 FL
23	1		*REAR END PANEL TOP GARNISH	Distorted	318.00 FL	*214.50 FL
24	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
25	2		*REAR FENDER	Badly Dented / Buckled	3,996.00 FL	*1,848.00 FL
26	1		*REAR FENDER INNER SHIELD	O/S Torn	352.00 FL	*176.00 FL
27	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	80.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR SPARE TYRE SIDE SPONGE	Torn	290.00 FL	*290.00 FL
29	1		*REAR SPARE TYRE TOP GARNISH	Not Necessary	368.00 FL	*- FL
30	1		*REAR SPARE TYRE PANEL	Repair	1,325.00 FL	*- FL
31	1		*REAR EXHAUST PIPE	Repair	1,425.00 FL	*- FL
32	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	175.00 FL	*- FL
33	1		*REAR EXHAUST CHROME MUFFLER	Not fitted	215.00 FL	*- FL
34	3		*REAR EXHAUST MOUNTING	Not Necessary	144.00 FL	*- FL
35	1		*FRONT BUMPER	Distorted	1,031.00 FL	*1,031.00 FL
36	1		*FRONT BUMPER TOP	No such part	138.00 FL	*- FL
37	2		*FRONT BUMPER SIDE RETAINER	Bent	184.00 FL	*130.00 FL
38	2		*FRONT BUMPER BRACKET	Not Necessary	150.00 FL	*- FL
39	2		*FRONT BUMPER SIDE GARNISH (INNER)	Torn	116.00 FL	*116.00 FL
40	2		*FRONT BUMPER FOG LAMP	Not Necessary	656.00 FL	*- FL
41	1		*FRONT BUMPER REINFORCEMENT	Bent	565.00 FL	*466.80 FL
42	1		*FRONT BUMPER REINFORCEMENT GARNISH	Torn	119.00 FL	*119.00 FL
43	1		*FRONT BUMPER NUMBER PLATE GARNISH	Distorted	95.00 FL	*66.50 FL
44	1		*FRONT BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
45	1		*RADIATOR GRILLE	Cracked	425.00 FL	*425.00 FL
46	1		*RADIATOR GRILLE LOGO	Cracked	112.00 FL	*46.50 FL
47	1		*RADIATOR GRILLE CHROME	O/S Cracked	386.00 FL	*185.60 FL
48	1		*RADIATOR GRILLE CLIPS	Not Necessary	35.00 FL	*- FL
49	1		*RADIATOR GRILLE TOP GARNISH	Distorted	298.00 FL	*298.00 FL
50	1		*RADIATOR GRILLE TOP GARNISH CLIPS	Necessary	40.00 FL	*40.00 FL
51	1		*BONNET PANEL	Buckled	1,186.00 FL	*1,067.30 FL
52	1		*BONNET SEAL	Necessary	112.00 FL	*63.00 FL
53	1		*BONNET LOCK	Jammed	386.00 FL	*197.00 FL
54	1		*FRONT SUPPORT PANEL	Cracked	495.00 FL	*493.70 FL
55	2		*HEADLAMP ASSY	Cracked	3,778.00 FL	*3,778.00 FL
56	2		*HEADLAMP LOWER BRACKET	No such part	250.00 FL	*- FL
57	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
58	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
59	1		*REAR SPARE TYRE PANEL INSULATOR	Not Necessary	250.00 FS	*- FS
60	1		*REAR EXHAUST GUM	Not Necessary	120.00 FS	*- FS
61	1		*RADIATO COOLANT	Necessary	120.00 FS	*30.00 FS
62	1		*FRONT NUMBER PLATE W/BASE GARNISH	Broken	65.00 FS	*40.00 FS
63	1		*REAR NUMBER PLATE W/BASE GARNISH	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	31,987.00	17,394.10
- List Item Discount on L Items 10.00/20.00% (S\$)	3,055.90	3,414.82

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	28,931.10
						13,979.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR & RENEW FRONT AFFECTED ACCIDENT AREAS	New	1,000.00	800.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,200.00	900.00
3	TO DISCHARGE & CHARGE UP GAS	New	120.00	100.00
4	TO REMOVE ,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,400.00	1,400.00
5	TO PUTTY ,SRPAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,400.00	1,100.00
6	TO REMOVE & INSTALL REAR EXHAUST TO FACILITATE REPAIRS	New	150.00	80.00
7	TO REMOVE & INSTALL REAR WINDSCREEN GLASS	New	150.00	120.00
8	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	30.00
9	TO REMOVE & INSTALL REAR BOOTLID COMPONENTS TRIM & GARNISH	New	150.00	60.00
10	TO REMOVE & INSTALL REAR FENDERS TRIM,GARNISH	New	150.00	80.00
11	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
12	TO RUST PROOF AFFECTED AREAS	New	200.00	120.00
Gross Labour Cost (S\$)			6,120.00	4,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >