5/24/2021 Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III21004597/BQF3E2

24/05/2021 Date:

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MFL0003414\_02

**Claimant Vehicle** FBR4337J Insured Vehicle No: SMY1306B

No:

Date of Loss: 22/03/2021 Nature of Claim: TP Claim No: MFL2021D0001250

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **FBR4337J** 

Make & Model: YAMAHA NMAX155, 155cc G3H6E0016794 Engine No: Reg. Date: 11/07/2020 (Man. Year: 2019) Chassis No: MH3SG431000013455

Colour: Odometer: 16020 km Blue

**Engine Capacity:** 155 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size: 110/70/13 Rear Tyre Size: 130/70/13 Front Left Side: Rear Left Side: Pirelli 6 mm Pirelli 6 mm Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,363.00	1,028.00	335.00	24.58
Miscellaneous Items		0.00	0.00	0.00	
Labour		550.00	250.00	300.00	54.55
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	1,913.00	1,278.00	635.00	33.19
	Approved Total (Overridden) (S\$)		1,000.00		
	Nett Amount (S\$)	1,913.00	1,000.00	913.00	47.73

**INSPECTION** 

Date of Assignment: 12/04/2021

Yp Motorsports Trading (HQ) Blk 9004 Tampines St 93, #01-92 Date Inspected: 13/04/2021 Inspected At:

Singapore 528836

Estimated Period of Repair: 4.0 days

Adjuster: Manager: SHIAU CHAN Lim Teow Guan

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/24/2021 Adjuster Report

## REPAIR DETAILS

Reference

**Part Source:** (Last Synchronised: 24 May 2021)

Parts: N/A YAMAHA NMAX155 155cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBR4337J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LEFT UPPER CROWING	Cut	180.00 FL	*180.00 FL
2	1		*FRONT LEFT CENTER CROWING	Cut	80.00 FL	*80.00 FL
3	1		*FRONT LEFT LOWER CENTER CROWING	Cut	150.00 FL	*150.00 FL
4	1		*FRONT LEFT LOWER CROWING	Cut	80.00 FL	*80.00 FL
5	1		*SIDE STAND	Cut	45.00 FL	*45.00 FL
6	1		*MAIN STAND	Not Necessary	120.00 FL	*- FL
7	1		*SET REAR FOOTREST (L/R)	Cut	45.00 FL	*45.00 FL
8	1		*FRONT FENDER	Cut	80.00 FL	*80.00 FL
9	1		*FRONT RIGHT UPPER CROWING	Cut	180.00 FL	*180.00 FL
10	1		*FRONT RIGHT CENTER CROWING	Cut	80.00 FL	*80.00 FL
11	1		*FRONT RIGHT LOWER CENTER CROWING	Repair	150.00 FL	*- FL
12	1		*FRONT RIGHT LOWER CROWING	Repair	80.00 FL	*- FL
13	1		*SET REAR VIEW MIRROR	Missing	35.00 FS	*35.00 FS
14	1		*SET BRAKE LEVER (L/R)	Scratched	70.00 FS	*70.00 FS
15	1		*PHONE HOLDER	Missing	65.00 FS	*45.00 FS
16	1		*SET FRONT WHEEL SLIDER	Cut	50.00 FS	*50.00 FS
F=Fra	nchise	part. S=SpcN	lett. L=ListItemDisc.	_		
				Sub Total (S\$)	1,490.00	1,120.00
			- List Item Discount on L Items	s 10.00/10.00% (S\$)	127.00	92.00
				Total Parts (S\$)	1,363.00	1,028.00

Report was unsubmitted during this print-out.

Adjuster Report

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TOWING	New	50.00	0.00
2	LABOUR CHARGE TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, INCLUDING REPAIRING, RE-FIXING, ADJUSTII CHECKING, ETC	New NG,	500.00	250.00
	Gross Lak	oour Cost (S\$)	550.00	250.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >