

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21004607/T1PS3Q2  
**Date:** 07/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993710
<b>Claimant Vehicle No :</b>	SHC6766Z	<b>Insured Vehicle No :</b>	YN3392D
Date of Loss:	10/04/2021	Nature of Claim:	TP
		Claim No:	6723528325SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHC6766Z</b>	Engine No:	D4FDEH313366
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5593421
Reg. Date:	30/04/2015 (Man. Year: 2014)	Odometer:	453994 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,197.40	214.40	3,983.00	94.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	1,270.00	1,360.00	51.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,827.40</b>	<b>1,484.40</b>	<b>5,343.00</b>	<b>78.26</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,150.00</b>		

## Adjuster Report

	(S\$)	6,827.40	1,150.00	5,677.40	83.16
<b>+ GST 7.00/7.00% (S\$)</b>		477.92	80.50	397.42	83.16
<b>Nett Amount (S\$)</b>		<b>7,305.32</b>	<b>1,230.50</b>	<b>6,074.82</b>	<b>83.16</b>
<b>+ Loss of Use (4.0 x S\$50.00/day) (S\$)</b>			200.00		
<b>+ Car Rental (4.0 x S\$67.76/day) (S\$)</b>			271.04		
	(S\$)		1,701.54		
<b>Liabe Amount (50.00%) (S\$)</b>			<b>850.77</b>		
<b>+ Doc/Search Fee (S\$)</b>			7.45		
			<b>858.22</b>		
<b>Global Sum Settlement (S\$)</b>			<b>800.00</b>		

INSPECTION

Date of Assignment: 12/04/2021

Date Inspected: 12/04/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)  
23 Changi South Ave 2, #01-02  
Singapore 486443**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	696.00 FL	*- FL
2	1		*REAR BUMPER O/S SIDE BRACKET	Not Necessary	16.00 FL	*- FL
3	1		*REAR O/S FENDER	Repair	1,205.00 FL	*- FL
4	1		*REAR O/S FENDER INNER SHIELD	Not Necessary	120.00 FL	*- FL
5	1		*REAR WINDSCREEN MOULDING	Not Necessary	87.00 FL	*- FL
6	1		*WHEEL COVER	Cracked	116.00 FL	*116.00 FL
7	1		*REAR O/S SHOCK ABSORBER	Not Necessary	313.00 FL	*- FL
8	1		*REAR O/S LOWER ARM	Not Necessary	351.00 FL	*- FL
9	1		*REAR O/S TRAILING ARM	Not Necessary	159.00 FL	*- FL
10	1		*REAR O/S KNUCKLE ARM	Not Necessary	525.00 FL	*- FL
11	1		*REAR O/S HUB BEARING	Not Necessary	349.00 FL	*- FL
12	1		*REAR O/S ASSIST ARM	Not Necessary	163.00 FL	*- FL
13	1		*REAR O/S RIM	Not Necessary	246.00 FL	*- FL
14	1		*SET REAR BUMPER CLIPS	Not Necessary	48.00 FS	*- FS
15	1		*SET O/S DOOR STICKER	Necessary	100.00 FS	*60.00 FS
16	1		*REAR O/S FENDER STICKER	Necessary	60.00 FS	*30.00 FS
17	1		*SET REAR O/S FENDER INNER SHIELD CLIPS	Not Necessary	28.00 FS	*- FS
18	1		*SUNDRY	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,632.00</b>	<b>226.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	434.60	11.60
<b>Total Parts (\$)</b>	<b>4,197.40</b>	<b>214.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE /REFIT REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	30.00
2	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ETC TO FACILITATE REPAIRS	New	180.00	60.00
3	TO CHECK WHEEL ALIGNMENT	New	80.00	80.00
4	TO DISMANTLE AND REPLACE REAR O/S UNDERCARRIAGE	New	180.00	0.00
5	TO DISMANTLE AND REFIT THE REAR WINDSCREEN	New	120.00	0.00
6	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .TO CUT /WELD AND HEAT ON THE REAR O/S FENDER .INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE REAR O/S DOOR ETC	New	1,000.00	400.00
7	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER ,REAR O/S FENDER ,REAR O/S DOOR ,O/S ROCKER PANEL GARNISH	New	800.00	700.00
8	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	150.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,630.00</b>	<b>1,270.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >