

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21004610/T1PA3Q2
Date: 08/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070171433
Claimant Vehicle No :	SHD3169L	Insured Vehicle No :	SGD6836L
Date of Loss:	11/04/2021	Nature of Claim:	TP
		Claim No:	2182976288SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3169L	Engine No:	D4FDGU655692
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU091842
Reg. Date:	08/07/2016 (Man. Year: 2016)	Odometer:	594444 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,144.12	1,256.60	887.52	41.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	530.00	620.00	53.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,294.12	1,786.60	1,507.52	45.76
Approved Total (Overridden) (S\$)		1,450.00		

(S\$)	3,294.12	1,450.00	1,844.12	55.98
+ GST 7.00/7.00% (S\$)	230.59	101.50	129.09	55.98
Nett Amount (S\$)	3,524.71	1,551.50	1,973.21	55.98
+ Car Rental (2.5 x S\$114.95/day) (S\$)		287.38		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,840.88		
Global Sum Settlement (S\$)		1,840.00		

INSPECTION

Date of Assignment: 12/04/2021

Date Inspected: 12/04/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Repair	1,052.20 FL	*- FL
2	1		*RADIATOR GRILLE	Cracked	1,480.00 FL	*1,480.00 FL
3	10		*BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
4	1		*FRONT BUMPER BRACKET TOP LH	Not Necessary	28.60 FL	*- FL
5	1		*FRONT BUMPER BRACKET SIDE LH	Not Necessary	28.60 FL	*- FL
6	1		*FRONT NUMBER PLATE W/HOLDER	Cracked	55.00 FS	*55.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,666.40	1,557.00
- List Item Discount on L Items 20.00/20.00% (\$)	522.28	300.40
Total Parts (\$)	2,144.12	1,256.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	280.00
2	SPRAY PAINTING	New	500.00	250.00
3	CHECK LIGHTING	New	50.00	0.00
Gross Labour Cost (\$\$)			1,150.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >