

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21003643/QVF3E2-1

Date: 29/04/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SJN5049K **Insured Vehicle No :** SLP8874R
Date of Loss: 17/03/2021 Nature of Claim: TP Claim No: MFL2021D0001160

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN5049K**
Make & Model: TOYOTA COROLLA, 1.5 X AXIO (A) Engine No: 1NZD179745
Reg. Date: 18/02/2009 (Man. Year: 2008) Chassis No: NZE1416095733
Colour: Blue Odometer: 163174 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,644.95	3,073.59	2,571.36	45.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,760.00	2,260.00	1,500.00	39.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,404.95	5,333.59	4,071.36	43.29
Approved Total (Overridden) (S\$)		4,250.00		
(S\$)	9,404.95	4,250.00	5,154.95	54.81
+ GST 7.00/7.00% (S\$)	658.35	297.50	360.85	54.81
Nett Amount (S\$)	10,063.30	4,547.50	5,515.80	54.81

INSPECTION

Date of Assignment: 12/04/2021
Date Inspected: 22/03/2021 Inspected At: Omega Auto Pte Ltd
160 Sin Ming Drive #06-06, Sin Ming Auto City
Singapore 575722
Estimated Period of Repair: 6.0 days

Adjuster: OI SUN PIN

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Apr 2021)
Parts:	143	TOYOTA COROLLA 1.5 X AXIO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN5049K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	823.00 F	*823.00 FL
2	1		*BOOT LID OUTER HANDLE / GARNISH	Cracked	159.60 F	*159.60 FL
3	1		*BOOT LID INNER LOCK ASSY	Jammed	75.61 F	*75.61 FL
4	1		*BOOT LID INNER LOCK CATCH	Serviceable	18.70 F	*- FL
5	1		*BOOT LID HINGES	O/S Bent	93.00 F	*46.50 FL
6	1		*BOOT LID INSULATOR COVER	Serviceable	212.60 F	*- FL
7	1		*BOOT LID EMBLEM	Necessary	42.50 F	*42.50 FL
8	1		*BOOT LID COROLLA STICKER	Necessary	26.60 F	*26.60 FL
9	1		*BOOT LID AXIO PLATE	Necessary	39.29 F	*39.29 FL
10	1		*BOOT LID X PLATE	Necessary	30.65 F	*30.65 FL
11	1		*BOOT WEATHERSTRIP	Crumpled	209.40 F	*209.40 FL
12	2		*REAR LAMPS ASSY	Cracked	650.00 F	*650.00 FL
13	1		*REAR PANEL	Bent	649.00 F	*561.00 FL
14	1		*REAR PANEL INNER GARNISH	Broken	227.20 F	*195.00 FL
15	1		*REAR BUMPER FASCIA	Crumpled	423.00 F	*423.00 FL
16	1		*REAR BUMPER BRACKETS	O/S Broken	114.00 F	*57.00 FL
17	1		*REAR BUMPER SIDE RETAINERS	O/S Broken	84.20 F	*42.10 FL
18	1		*REAR BUMPER CORNER RETAINERS	O/S Broken	76.20 F	*38.10 FL
19	1		*REAR EXHAUST PIPE ASSY	Serviceable	865.30 F	*- FL
20	2		*REAR EXHAUST MOUNTINGS	Serviceable	37.00 F	*- FL
21	1		*BOOT FLOOR TOP COVER	Crumpled	248.10 F	*248.10 FL
22	1		*SET BOOT LID OUTER HANDLE / GARNISH CLIPS	Necessary	20.00 FS	*14.00 FS
23	1		*SET BOOT LID INSULATOR COVER CLIPS	Serviceable	50.00 FS	*- FS
24	1		*REAR PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
25	1		*SET REAR PANEL INNER GARNISH CLIPS	Necessary	20.00 FS	*14.00 FS
26	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*35.00 FS
27	1		*SET REVERSE SENSORS	O/S Shorted	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,644.95	3,990.45
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	916.86
Total Parts (\$\$)	5,644.95	3,073.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE BOOT LID FITTINGS, CHECK, RENEW DAMAGED FITTINGS, TRANSFER ALL FITTINGS TO NEW BOOT LID ASSY AND REFIT	New	150.00	60.00
2	REMOVE NECESSARY INTERIOR UPHOLSTERY AND FITTINGS TO ENABLE NECESSARY REPAIRS, CHECK AND REFIT SAME	New	150.00	80.00
3	REMOVE LAMPS, NECESSARY WIRINGS AND ELECTRICAL FITTINGS TO ENABLE NECESSARY REPAIRS, CHECK, REPLACE DAMAGED PARTS, REFIT SAME, TEST ELECTRICAL-CIRCUIT	New	60.00	30.00
4	RENEW REVERSE SENSORS, TRANSFER SAME TO NEW BUMPER ASSY., REFIT AND CALIBRATE SYSTEM	New	100.00	50.00
5	REMOVE EXHAUST PIPE SYSTEM, CHECK, REPLACE DAMAGED PARTS AND REFIT SAME	New	100.00	40.00
6	REMOVE DAMAGED PARTS, JACK AND CUT OUT DAMAGED BODY PANELS, JACK OUT, STRAIGHTEN UP DAMAGED BODY PANELS AND REPAIR BODY PARTS AND FITTINGS, WHICHEVER POSSIBLE AND NECESSARY, REPLACE AND WELD NECESSARY DAMAGED PARTS, REFIT AND ALIGN WHICHEVER PARTS NECESSARY. (INCL. ALIGNMENT OF BODY STRUCTURE)	New	1,400.00	1,000.00
7	PAINT REPLACEMENT PARTS AND REPAINT DAMAGED SECTIONS WITH WELDED PORTIONS IN AND OUTSIDE	New	1,600.00	1,000.00
8	RUSTPROOF REPLACEMENT PARTS AND TOUCH-UP DAMAGED SECTIONS	New	200.00	0.00
Gross Labour Cost (\$\$)			3,760.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >