#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21004623/EVF3E2

**Date:** 26/04/2021

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070053281

Claimant Vehicle No: SMK1830C Insured Vehicle No: SMS9674S

Date of Loss: 09/04/2021 Nature of Claim: TP Claim No: 4568507040SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMK1830C

 Make & Model:
 HONDA VEZEL, 1.5 (A)
 Engine No:
 LEB6742720

 Reg. Date:
 29/03/2019 (Man. Year: 2018)
 Chassis No:
 RU31322710

Colour: Blue Odometer: 0 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Double Star 4 mm Rear Left Side: Double Star 4 mm
Front Right Side: Double Star 4 mm

Rear Right Side: Double Star 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

**INSPECTION** 

Date of Assignment: 12/04/2021

Apex Motoring

Date Inspected: 13/04/2021 Inspected At: 25 Kaki Bukit Road 4, #01-55 Synergy @ KB

Singapore 417800

Estimated Period of Repair: 18.0 days

Adjuster: CHEN TSUE YEE Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRT NUMBER PLATE	Broken	0.00 F	*- F
2	1	*FRT NUMBER PLATE BASE	Broken	0.00 F	*- F
3	1	*FRT BUMPER	Broken	0.00 F	*- F
1	1	*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	2	*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
3	1	*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F
7	1	*FRT BUMPER LOWER SPOILER	Broken	0.00 F	*- F
8	1	*FRT LH BUMPER FOG LAMP COVER	Cut	0.00 F	*- F
9	1	*FRT RH BUMPER FOG LAMP COVER	Cut	0.00 F	*- F
10	1	*FRT LH BUMPER FOG LAMP	Broken	0.00 F	*- F
11	1	*FRT RH BUMPER FOG LAMP	Broken	0.00 F	*- F
12	1	*FRT GRILLE	Broken	0.00 F	*- F
13	1	*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
14	1	*FRT GRILLE CHROME MOULDING	Broken	0.00 F	*- F
15	1	*FRT SUPPORT PANEL	Dented	0.00 F	*- F
16	1	*FRT SUPPORT PANEL TOP GARNISH COVER	Broken	0.00 F	*- F
17	1	*HORN	Broken	0.00 F	*- F
18	1	*FRT LH HEADLAMP ASSY	Broken	0.00 F	*- F
19	1	*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
20	2	*FRT LH HEADLAMP BRACKET	Broken	0.00 F	*- F
21	1	*BONNET	Dented	0.00 F	*- F
22	1	*BONNET LOCK BRACKET	Broken	0.00 F	*- F
23	1	*BONNET LOCK	Bent	0.00 F	*- F
24	1	*BONNET INSULATOR	Crushed	0.00 F	*- F
25	2	*BONNET HINGE	Bent	0.00 F	*- F
26	1	*AIR CON CONDENSER	Dented	0.00 F	*- F
27	1	*AIR CON FAN ASSY	Broken	0.00 F	*- F
28	1	*RADIATOR	Dented	0.00 F	*- F
29	1	*RADIATOR FAN ASSY	Broken	0.00 F	*- F
29 30	1	*RADIATOR EXPANSION TANK	Crushed	0.00 F	- r *- F
30 31	1	*AIR CLEANER HOSE	Crushed	0.00 F	*- F
32	1	*FRT EXHAUST MANIFOLD	Crusned	0.00 F	-г *- F
		*WIPER WASHER TANK			-г *-F
33	1		Crushed	0.00 F	
34	1	*FRT RH CHASSIS MEMBER	Dented	0.00 F	*-F
35	1	*FRT LH FENDER	Dented	0.00 F	*- F
36	1	*FRT LH FENDER PROTECTOR ARCH	Broken	0.00 F	*- F
37	1	*FRT RH FENDER	Dented	0.00 F	*- F
38	1	*FRT RH FENDER PROTECTOR ARCH	Broken	0.00 F	*- F
39	1	*REAR NUMBER PLATE	Cut	0.00 F	*- F
40	1	*REAR NUMBER PLATE BASE	Cut	0.00 F	*- F
41	1	*REAR BUMPER	Broken	0.00 F	*- F
12	2	*REAR BUMPER SIDE	Crushed	0.00 F	*- F
43	1	*REAR BUMPER TOW COVER	Crushed	0.00 F	*- F
44	1	*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
45	2	*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
46	1	*REAR BUMPER REFLECTOR	Broken	0.00 F	*- F
17	1	*REVERSE SENSOR	Broken	0.00 F	*- F
48	1	*REAR END PANEL	Dented	0.00 F	*- F
49	1	*REAR END PANEL TOP GARNISH	Crushed	0.00 F	*- F
50	1	*REAR LH TAILLAMP	Broken	0.00 F	*- F
51	1	*REAR RH TAILLAMP	Cut	0.00 F	*- F
52	1	*TAILGATE	Dented	0.00 F	*- F
53	1	*TAILGATE EMBLEM	Necessary	0.00 F	*- F
54	1	*TAILGATE GARNISH	Broken	0.00 F	*- F
					*- F

Report was unsubmitted during this print-out.

No.	Qty I	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*TAILGATE TRIM BOARD	Crushed	0.00 F	*- F
57	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
58	1		*TAILGATE LOCK	Bent	0.00 F	*- F
59	1		*TAILGATE RUBBER	Torn	0.00 F	*- F
60	1		*SPARE TYRE BOARD	Crushed	0.00 F	*- F
61	1		*SPARE TYRE PANEL	Dented	0.00 F	*- F
62	1		*SPARE TYRE UNDER COVER	Crushed	0.00 F	*- F
63	1		*SPARE TYRE TRAY	Crushed	0.00 F	*-F
64	1		*REAR EXHAUST PIPE	Bent	0.00 F	*- F
65	1		*REAR EXHAUST HEAT SHIELD	Bent	0.00 F	*-F
66	1		*REAR LH FENDER PROTECTOR ARCH	Broken	0.00 F	*- F
67	1		*REAR LH FENDER INNER TRIM	Crushed	0.00 F	*-F
68	1		*REAR RH FENDER	Dented	0.00 F	*- F
69	1		*REAR RH FENDER PROTECTOR ARCH	Broken	0.00 F	*-F
70	1		*REAR RH FENDER INNER TRIM	Crushed	0.00 F	*- F
71	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
72	1		*BUZZLE	Broken	0.00 F	*- F
F=Fra	nchise p	art.		_		
				Total Parts (S\$)	0.00	0.00
			Report was unsubmitted during	this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >