

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21004626/KTF3N2**Date:** 01/11/2021**REFERENCE**

Insured/Claimant:	Jet Cool Air Conditioning & Enterprise	Policy No:	2070136351
Date of Loss:	09/04/2021	Nature of Claim:	OD Claim No: 0990498530SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF4764Y		
Make & Model:	TOYOTA HIACE, 1.8 D SUPER GL DARK PRIME (A)	Engine No:	1KD2655259
Reg. Date:	08/11/2016 (Man. Year: 2016)	Chassis No:	JTFHT02P400207471
Colour:	White	Odometer:	103166 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$52,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8
Front Left Side:	Bearway 6 mm	Rear Left Side:	Bearway 7 mm
Front Right Side:	Bearway 6 mm	Rear Right Side:	Bearway 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,457.72	3,321.00	1,136.72	25.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,620.00	1,330.00	1,290.00	49.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,077.72	4,651.00	2,426.72	34.29
Approved Total (Overridden) (S\$)		3,700.00		
- Excess (S\$)	800.00	800.00	0.00	0.00
Nett Amount (S\$)	6,277.72	2,900.00	3,377.72	53.80

INSPECTION

Date of Assignment:	12/04/2021	
Date Inspected:	13/04/2021	Inspected At: Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	459.70 FL	*459.70 FL
2	1		*FRONT BUMPER SIDE CLIPS	O/s Distorted	46.00 FL	*23.00 FL
3	1		*RH HEADLAMP	Mtg Cracked	704.15 FL	*704.15 FL
4	1		*FRONT RH CORNER PANEL	Buckled	258.10 FL	*258.10 FL
5	1		*SET FRONT WINDSCREEN MOULDING	Not Necessary	110.20 FL	*- FL
6	1		*FRONT RH DOOR	Bent	1,410.35 FL	*1,410.35 FL
7	1		*FRONT RH DOOR RUBBER	Cut	121.05 FS	*80.70 FS
8	1		*FRONT RH DOOR INNER LOCK	Repair	509.23 FL	*- FL
9	1		*FRONT RH DOOR INNER LOCK CATCH	Repair	65.20 FL	*- FL
10	1		*FRONT RH DOOR INNER TRIM BOARD	Mtg Cracked	780.15 FL	*780.15 FL
11	1		*SET FRONT RH DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FL	*50.00 FL
12	2		*FRONT RH DOOR HINGE (TOP & BOTTOM)	Bent	148.60 FL	*148.60 FL
13	1		*FRONT RH DOOR CHECKER	Bent	120.45 FL	*120.45 FL
14	1		*FRONT RH DOOR GLASS OUTER MOULDING	Serviceable	156.56 FL	*- FL
15	1		*FRONT RH DOOR GLASS CHANNEL	Cut	153.76 FS	*102.51 FS
16	1		*FRONT RH DOOR PILLAR (OUTER)	Repair	435.96 FL	*- FL
17	1		*FRONT RH DOOR PILLAR RUBBER	Cut	202.56 FL	*202.56 FL
18	1		*SET FRONT WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
19	1		*FRONT RH DOOR LOWER BLACK COMPANY STICKER	Necessary	40.00 FS	*20.00 FS
					Sub Total (\$)	5,822.02 4,360.27
					- List Item Discount on L Items 25.00/25.00% (\$)	1,364.30 1,039.27
					Total Parts (\$)	4,457.72 3,321.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES FOR REMOVE/REFIT AND REPLACE DAMAGE PARTS	New	1,000.00	600.00
2	TO PUTTY AND SPRAY SPRAY PAINTINGS CHARGES	New	1,000.00	650.00
3	TO REMOVE,REFIT FRONT WINDSCREEN GLASS	New	140.00	0.00
4	TO CHECK WIRINGS AND LIGHTINGS	New	40.00	20.00
5	TO REMOVE,REFIT DOOR FITTINGS	New	80.00	60.00
6	TO REMOVE,REFIT DASHBOARD ASSY	New	280.00	0.00
7	TO SUPPLY AND APPLY RUST PROOFING TREATMENTS	New	80.00	0.00
Gross Labour Cost (\$)			2,620.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >