

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
Lum Tse Meng Benny		Cust No/Name	/Lum Tse Meng Benny
61 Soo Chow Garden Road		Reg No/Reg Date	SKS9087K / 14/05/201
Singapore 575512		Date In/Mileage	/ 0
		Chassis No	JMYXTGF3WFZ002166
		Engine No	4B12PM4096
		Make/Model	MIT/OUTLANDER 2.4 CVT AWD (F27)
Contact No Mobile: 96194049		Colour/Trim	U01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	09/03/2021/ 10:04	QUK	282 / Kevin Leong	63779

Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	REPLACE FRT ⁸⁰ LH DOOR, LH AIR DAM, RR LH PANEL MOULDING & AFFECTED AREA 1 1/2 +80				755 2880.00
E PNT98000	REPAIR ON REAR LH DOOR & REAR LH FENDER ^{1/2}				1050 2200.00
E PNT88000	PAINT WORK ON FRT LH DOOR, REAR LH DOOR & REAR LH FENDER 3				120 180.00
M SUNDRY	TO TRANSFER FRT LH DOOR ATTACHMENTS TO NEW PANEL				40 150.00
M SUNDRY	PERFORM RUST PREVENTION				-50.00
M SUNDRY	TO APPLY SEALANT ON AFFECTED AREA				30 120.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				120 280.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				20 50.00
M SUNDRY	USING HI-SCAN PRO TEST				
M SUNDRY	SUNDRIES				
M PANEL ASSY,FR DOOR,LH	1.00	1138.00	00.00		1138.00
M MLDG,F/DR WDO BELT LINE,LH	1.00	130.00	00.00		130.00
M W/STRIP,FR DR OPNG,OTR LH	1.00	168.00	00.00		168.00
M W/STRIP,F/DR OPENG,LWR LH	1.00	47.00	00.00		47.00
M AIR DAM,SIDE,LH	1.00	544.00	00.00		544.00
M TAPE,FR DOOR SASH,LH	1.00	42.00	00.00		42.00
M MOULDING,RR WHEEL ARCH,LH	1.00	199.00	00.00		199.00
M MOULDING,RR BUMPER,LH	1.00	106.00	00.00		106.00

Estimate

Store CLKK)
12/4/21, 2.00pm
00- NM ML
Excess - ?
P/P

Confirm & accepted by

	Nett	8,284.00
7% GST on	8284.00	579.88

Total Payable	8.863.88
----------------------	-----------------

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.