

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21004630/ETF3E2**Date:** 05/07/2021**REFERENCE**

Insured/Claimant:	ONG POH KIM	Policy No:	2070053281	
Date of Loss:	09/04/2021	Nature of Claim:	OD	Claim No: 4568507040SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS9674S		
Make & Model:	CITROEN C5, 1.6 (A)	Engine No:	10FKBA2586146
Reg. Date:	24/03/2020 (Man. Year: 2019)	Chassis No:	VR7A45GFRKL097282
Colour:	Black	Odometer:	13314 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$115,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R17	Rear Tyre Size:	235/60 R17
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,076.40	12,611.20	1,465.20	10.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,275.00	6,755.00	520.00	7.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,351.40	19,366.20	1,985.20	9.30
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	21,051.40	19,066.20	1,985.20	9.43
+ GST 7.00/7.00% (S\$)	1,473.60	1,334.63	138.97	9.43
Nett Amount (S\$)	22,525.00	20,400.83	2,124.17	9.43

INSPECTION

Date of Assignment:	12/04/2021	
Date Inspected:	12/04/2021 Inspected At:	Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ) 209 PANDAN GARDENS Singapore 609339
Estimated Period of Repair:	10.0 days	

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
2	1		*FRT LIGHT LH (NPA)	Not Necessary	0.00 FS	*- FS
3	1		*FRT LIGHT RH (NPA)	Not Necessary	0.00 FS	*- FS
4	1		*FRONT BUMPER	Dented	1,488.00 FL	*1,488.00 FL
5	1		*FR BMPR GRILLE	Broken	809.00 FL	*809.00 FL
6	1		*SET BRACKET	Broken	108.00 FL	*108.00 FL
7	1		*FINISHER BUMPER	Necessary	92.00 FL	*92.00 FL
8	1		*FR BMPR GRILLE CENT	Cracked	131.00 FL	*131.00 FL
9	1		*FR BMPR GRILLE LAT	Cracked	147.00 FL	*147.00 FL
10	1		*FINISHER BUMPER LAT	Cut	182.00 FL	*182.00 FL
11	1		*FINISHER BUMPER	Cut	115.00 FL	*115.00 FL
12	1		*FR BMPR GRILLE IN	Cut	229.00 FL	*229.00 FL
13	1		*BUMPER ABSORBER	Broken	155.00 FL	*155.00 FL
14	1		*SET BRACKET	Necessary	108.00 FL	*108.00 FL
15	1		*REAR DUCT	Not Necessary	87.00 FL	*- FL
16	1		*RECESS DOOR	Crushed	80.00 FL	*80.00 FL
17	1		*BUMPER ABSORBER	Not Necessary	367.00 FL	*- FL
18	1		*BUMPER ABSORBER	Bent	495.00 FL	*495.00 FL
19	1		*FIXING STUD	Necessary	36.00 FL	*36.00 FL
20	1		*FACE CROSSMEMBR SUP	Broken	199.00 FL	*199.00 FL
21	1		*FACING SUPPORT LH ASSY	Not Necessary	90.00 FL	*- FL
22	1		*FACING SUPPORT RH ASSY	Not Necessary	94.00 FL	*- FL
23	1		*FACE CROSSMEMBER INF	Not Necessary	91.00 FL	*- FL
24	1		*FRONT WING LH ASSY	Dented	535.00 FL	*535.00 FL
25	1		*FRONT WING RH ASSY	Dented	535.00 FL	*535.00 FL
26	1		*WING MOULDING LH AILES AVANT	Necessary	213.00 FL	*213.00 FL
27	1		*WING MOULDING RH AILES AVANT	Necessary	213.00 FL	*213.00 FL
28	1		*ENGINE BONNET ASSY	Dented	1,351.00 FL	*1,351.00 FL
29	1		*BONNET HINGE LH	Not Necessary	118.00 FL	*- FL
30	1		*BONNET HINGE RH	Not Necessary	118.00 FL	*- FL
31	1		*BONNET LOCK	Not Necessary	37.00 FL	*- FL
32	1		*HOOD HOOK	Not Necessary	87.00 FL	*- FL
33	1		*PROTECTOR FERMERURE CAPOT	Not Necessary	211.00 FL	*- FL
34	1		*SOUND PROOFING	Crushed	290.00 FL	*290.00 FL
35	1		*HEADLIGHT ASSY LH	Deformed	685.00 FL	*685.00 FL
36	1		*HEADLIGHT ASSY RH	Deformed	685.00 FL	*685.00 FL
37	1		*HDLIGHT SUPPORT LH COMPLEMENTA	Cut	72.00 FL	*72.00 FL
38	1		*HDLIGHT SUPPORT RH COMPLEMENTA	Cut	72.00 FL	*72.00 FL
39	1		*LIGHT MOULDING LH AV	Cut	89.00 FL	*89.00 FL
40	1		*LIGHT MOULDING RH AV	Cut	89.00 FL	*89.00 FL
41	2		*FOG HEADLIGHT	Not Necessary	254.00 FL	*- FL
42	1		*CONDENSER	Bent	907.00 FL	*907.00 FL
43	1		*CONDENSER BRACKET	Not Necessary	57.00 FL	*- FL
44	1		*RADIATOR NEW	Bent	649.00 FL	*649.00 FL
45	2		*FIXING BRACKET	Not Necessary	38.00 FL	*- FL
46	1		*FIXING BRACKET	Not Necessary	21.00 FL	*- FL
47	1		*MOTOR-DRIVN FAN	Broken	716.00 FL	*716.00 FL
48	1		*FAN CONTROL	Not Necessary	149.00 FL	*- FL
49	1		*AIR INTK GRILLE LH	Torn	197.00 FL	*197.00 FL
50	1		*BUMPER BRACKET (Supplementary)	Bent	339.00 FL	*339.00 FL
51	1		*AIR BULKHEAD LH (Supplementary)	Cracked	137.00 FL	*137.00 FL
52	1		*AIR BULKHEAD RH (Supplementary)	Cracked	137.00 FL	*137.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
53	1		*FRONT LIGHT LH (Supplementary)	Cracked	642.00 FL	*642.00 FL
54	1		*WDSCRN MOULDING RH (Supplementary)	Cut	289.00 FL	*289.00 FL
55	1		*WDSCRN MOULDING LH (Supplementary)	Cut	289.00 FL	*289.00 FL
56	1		*DRIP MOULDING LH (Supplementary)	Cut	58.00 FL	*58.00 FL
57	1		*DRIP MOULDING RH (Supplementary)	Cut	58.00 FL	*58.00 FL
58	1		*CONDENSER (Supplementary)	Dented	1,165.00 FL	*1,165.00 FL
59	1		*COOLING LIQUID DRUM 3L PAE -35(X2) (Supplementary)	Necessary	48.00 FL	*48.00 FL
60	1		*REAR DUCT (Supplementary)	Broken	166.00 FL	*166.00 FL
61	1		*FRONT LIGHT RH (Supplementary)	Cracked	642.00 FL	*642.00 FL
62	1		*DEFLECTOR (Supplementary)	Broken	97.00 FL	*97.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,588.00	15,759.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,511.60	3,147.80
Total Parts (\$\$)	14,076.40	12,611.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, BONNET, LHF FENDER, RHF FENDER & FRT SUPPORT. REPAIR LHF DOOR & RHF DOOR	New	3,000.00	2,500.00
2	RESPRAY FRT BUMPER, BONNET, LHF FENDER, RHF FENDER, LHF DOOR & RHF DOOR	New	2,280.00	2,280.00
3	RENEW AIRCON CONDENSER & RADIATOR	New	100.00	100.00
4	TOP UP AIRCON GAS	New	550.00	550.00
5	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	50.00	50.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	225.00	225.00
7	SUPPLY FRT NUMBER PLATE WITH CASING	New	50.00	50.00
8	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	80.00
9	SUPPLY BODY PNL SEALANT	New	80.00	60.00
10	APPLY ZERTONE PAINT PROTECTION IN AFFECTED AREAS	New	480.00	480.00
11	RESPRAY ON BOTH FRONT FENDER APRON (Supplementary)	New	380.00	380.00
Gross Labour Cost (\$\$)			7,275.00	6,755.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >