



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving TPVD Mercedes (SJE69H)

Date of Loss 12 April 2021

Time of Loss 14:15

Loss Description SKA884E (INSD) C/W SJE69H

Comment

Workshop Details

Total Rebate
Amount

0

Nett Loss Amount \$0.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work
completion *

20



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SJE69H

Purchase Date

DD/MM/YYYY



Registration State

SINGAPORE

Registration Date *

23/04/2018



Mileage

Age of Vehicle

2

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2017

Driver Details

CATEGORY



FNOL INFORMATION

POST SURVEY
INFORMATION


Driver Name

KOH TONG
LIANG

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD	<input type="text" value="MERCEDES BENZ"/>
Model	Mercedes	<input type="text" value="C200 COUPE A/T ABS L"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="WDD2053422F642523"/>
Engine No		<input type="text" value="27492031211696"/>
Engine Capacity		<input type="text" value="1991"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth		<input type="text" value="DD/MM/YYYY"/> 
Age	0	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text"/> ▼
Gender	Unknown	<input type="text"/> ▼
Marital status	Unknown	<input type="text"/> ▼
Identification #	TBC	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

13/04/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

225/45ZR18

Front left side

BRIDGESTONE7mm

Front right side

BRIDGESTONE7mm

Spare wheel

Rear Tyre Size

245/40R18

Rear left side

BRIDGESTONE7mm

Rear right side

BRIDGESTONE7mm



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

10

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

P
a
r
t
S
u
p
p
l
i
e
d
b
y

Save



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio










Parts & Labour











Miscellaneous










Summary


Parts

Add		Approve		Deny		Submit All							
EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR BOOTLID	Repair	0	0	No	0	0	0	0	0
	0	1		REAR BOOTLID LOCK	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BOOTLID EMBLEM "C200"	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BOOTLID OUTER LOCK C/W "BENZ"	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BOOTLID LAMP (LED) - LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER	Damaged	0	1894.18	No	0	10	0	0	1704.76
	0	1		REAR BUMPER REFLECTOR - LH (BOTTOM)	Cracked	0	125	No	0	10	0	0	112.5

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR BUMPER COVER GRILLE - LH (SIDE)	Broken	0	150	No	0	10	0	0	135
	0	2		REAR BUMPER SENSOR (3PCS)	Shorted	0	215	No	0	10	0	0	387
	0	1		REAR BUMPER SENSOR WIRING HARNESS	Damaged	0	262.35	No	0	10	0	0	236.12
	0	1		REAR BUMPER LOWER GARNISH	Damaged	0	366.57	No	0	10	0	0	329.91
	0	1		REAR BUMPER LOWER SPOILER	Deformed	0	820	No	0	10	0	0	738
	0	1		REAR BUMPER EXHAUST BRACKET CHROME COVER - LH	Bent	0	265.1	No	0	10	0	0	238.59
	0	1		REAR BUMPER EXHAUST CHROME COVER - LH	Bent	0	250	No	0	10	0	0	225
	0	2		REAR BUMPER NUMBER PLATE LAMP	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER CENTRE BRACKET	Serviceable	0	0	No	0	0	0	0	0















EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR BUMPER SIDE RETAINER - LH	Cracked	0	145	No	0	10	0	0	130.5
	0	1		REAR BUMPER REINFORCEMENT BAR	Bent	0	790.9	No	0	10	0	0	711.81
	0	1		REAR BUMPER KEYLESS SENSOR	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR FENDER - LH	Cracked	0	2964.1	No	0	10	0	0	2667.69
	0	1		REAR FENDER LAMP - LH (LED)	Cracked	0	755	No	0	10	0	0	679.5
	0	1		REAR FENDER LAMP LOWER BRACKET - LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR FENDER LAMP PANEL - LH	Repair	0	0	No	0	0	0	0	0
	0	1		REAR FENDER INNER TRIM - LH	Deformed	0	690.3	No	0	10	0	0	621.27
	0	1		REAR FENDER INNERSHIELD - LH (REAR)	Damaged	0	298.2	No	0	10	0	0	268.38
	0	1		REAR FENDER INNERSHIELD - LH (FRONT)	Serviceable	0	0	No	0	0	0	0	0



EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR FENDER INNER AIR VENT	Cracked	0	132.1	No	0	10	0	0	118.89
	0	1		REAR FENDER CONTROL UNIT COMPLETE (WINDOW REGULATOR)	Cracked	0	524.18	No	0	10	0	0	471.76
	0	1		REAR FENDER CONTROL UNIT COMPLETE BRACKET	Bent	0	325	No	0	10	0	0	292.5
	0	1		REAR FENDER CONTROL UNIT COMPLETE (REMOTE TRUNK RELEASE)	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR FENDER CONTROL UNIT COMPLETE (KEYLESS GO SENSOR)	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR EXHAUST HEATER SHIELD - LH	Bent	0	422	No	0	10	0	0	379.8
	0	1		REAR EXHAUST PIPE	Bent	0	1824.17	No	0	10	0	0	1641.75
	0	1		WEATHERSTRIP	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR WINDSCREEN MOULDING	Necessary	0	175	No	0	10	0	0	157.5

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR FENDER GLASS MOULDING	Necessary	0	60	No	0	10	0	0	54

Labour

Add	Approve	Deny	Submit All
-----	---------	------	------------

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO CHECK ELECTRICAL WIRING, RECTIFY AND CHECK FUNCTIONS	0	30	0	0	Reviewing		
	0		TO REMOVE AND REFIX REAR WINDSCREEN GLASS	0	120	0	0	Reviewing		
	0		TO REMOVE AND REFIX REAR FENDER GLASS	0	60	0	0	Reviewing		
	0		TO REMOVE AND TRANSFER BOOT LID COMPONENTS / PARTS	0	0	0	0	Deny		
	0		TO REMOVE AND REPLACE INTERIOR UPHOLSTERY AND INNER TRIM	0	80	0	0	Reviewing		
	0		TO REFIX AND REPLACE REVERSE SENSOR AND REVERSE CAMERA	0	50	0	0	Reviewing		
	0		TO REMOVE, REPAIR AND REFIX REAR EXHAUST BOX / SILENCER AND MOUNTINGS	0	80	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO CARRY OUT DIAGNOSTIC / SCANNING, RESETTNG AND REPROGRAMME AND CLEAR FAULT CODES	0	200	0	0	Reviewing		
	0		TO RESPRAY UNDERCOATING / RUST PROOFING AFFECTED AREAS	0	60	0	0	Reviewing		
	0		TO PUTTY, RESPRAY PAINTING, POLISH AFFECTED AREAS ETC	0	900	0	0	Reviewing		
	0		PANEL BEATING, STRAIGHTEN, CUT, WELD, REMOVE, REFIT AND REPLACING ABOVE PARTS	0	1200	0	0	Reviewing		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNTADJUSTED
AMOUNT

COMMENT

REMOVE



0

DAYS OF
REPAIR : 10
DAYS

Reviewing

0

0



0

REAR
BUMPER
CLIPS









Reviewing







0

60

NECESSARY



EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR BUMPER LOWER GARNISH CLIPS	Deny	0	0	NOT NECESSARY	
	0	REAR BUMPER LOWER SPOILER CLIPS	Deny	0	0	NOT NECESSARY	
	0	REAR BUMPER EXHAUST CHROME COVER CLIPS	Deny	0	0	NOT NECESSARY	
	0	REAR FENDER INNERSHIELD - LH CLIPS	Reviewing	0	30	NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR EXHAUST PIPE MOULDING (2PCS)	Deny	0	0	NOT NECESSARY	
	0	REAR WINDSCREEN SEALANT	Reviewing	0	40	NECESSARY	
	0	REAR FENDER GLASS SEALANT	Reviewing	0	30		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim
Amount

\$0.00

Adjusted Claim Amount

\$15,242.23

CATEGORY

ESTIMATE

ADJUSTED

Spare Parts

Labour

Spare Parts

Miscellaneous

[Submit for Review](#)



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNTADJUSTED
AMOUNT

COMMENT

REMOVE



0

FINAL
LUMP
SUM

Reviewing

0

12000





Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim
Amount

\$0.00

Adjusted Claim Amount

\$12,000.00

CATEGORY

ESTIMATE

ADJUSTED

Miscellaneous

Submit for Review